

Address	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0	Function	Range
00H	SS3	SS2	SS1	SS0	0	0	0	SQWS	Subseconds0	00-F0h
01H	SS11	SS10	SS9	SS8	SS7	SS6	SS5	SS4	Subseconds1	00-FFh
02H	S7	S6	S5	S4	S3	S2	S1	S0	Seconds0	00-FFh
03H	S15	S14	S13	S12	S11	S10	S9	S8	Seconds1	00-FFh
04H	S23	S22	S21	S20	S19	S18	S17	S16	Seconds2	00-FFh
05H	S31	S30	S29	S28	S27	S26	S25	S24	Seconds3	00-FFh
06H	ALM 7	ALM 6	ALM 5	ALM 4	ALM 3	ALM 2	ALM 1	ALM 0	Alarm0	00-FFh
07H	ALM 15	ALM 14	ALM 13	ALM 12	ALM 11	ALM 10	ALM9	ALM 8	Alarm1	00-FFh
08H	ALM 23	ALM 22	ALM 21	ALM 20	ALM 19	ALM 18	ALM 17	ALM 16	Alarm2	00-FFh
09H	ALM 31	ALM 30	ALM 29	ALM 28	ALM 27	ALM 26	ALM 25	ALM 24	Alarm3	00-FFh
0AH	TE	ECOSC	CCFG1	CCFG0	EPOL	SQWE	PIE	AIE	ControlA	00-FFh
0BH	PRS3	PRS2	PRS1	PRS0	SRS3	SRS2	SRS1	SRS0	ControlB	00-FFh
0CH	OSF	UIP	0	0	0	0	PF	ALMF	Status	--

In either of these applications, it is usually necessary to read the ETC while it is running. The DS1318 has a set of "user registers" that allow accessing the data while the internal counters continue to run. The user registers are updated from the internal registers every 244 μ s. Even though the counters are buffered, because the reads and counter updates can occur asynchronously, it is possible to read or write incorrect data.

Example 1

While reading the ETC, the data may update. If, for instance, the data in the registers was 0x55555555.FFF and an update occurred between reading the subseconds and seconds registers, the value read would be 0x55555556.FFF instead of 0x55555556.000.

Example 2

The data are transferred from the internal counters to the user registers as one of the registers is accessed. In this case, there is a window of a few nanoseconds where the data are changing just as they are being read. While the chances of this happening are low, the data, when it does occur, will be invalid.

Example 3

A write occurs while the data is being transferred between the internal counters and the user registers. Because the internal data bus is being used during the transfer, a write to any register in the DS1318 could corrupt the data (data collision). Again, the window when this can occur is only a few nanoseconds. The data in the user registers will be invalid until the next update, 244 μ s later.

Example 4

When writing the counter, if writing all the registers takes longer than 244 μ s, an update could occur, incrementing the data in previously written registers.

There are several ways to avoid these errors. The DS1318 contains two bits that can be used to avoid reading or writing during an update. The following paragraphs discuss the various methods.

An update could occur when reading the counter registers. One way to verify that the data read is correct is to read the appropriate registers, from LSB to MSB, store the results, and then read the

registers again. If an update has occurred, the data from the first read will be different from the second read. If the data is different, the registers should be read again until the data match. If all the subseconds registers are used, an update will occur every 244 μ s. If only the seconds registers are being used, an update will occur once per second (**Figure 1**).




Figure 1. Reading the clock registers between updates.

When reading the counters, the update-in-progress (UIP) bit can be used to avoid an error. The UIP cycles every 244 μ s, and will read back as a 1 if an update occurs within 61 μ s. When reading the

counter registers, the UIP bit should be checked. If it is 1, the reads should be delayed until UIP is 0. If UIP is 0, the registers can be read. The registers should be read within 60µs to avoid an update (**Figure 2**). If it is possible for the read routine to take longer than 60µs (i.e., the routine is interrupted by another routine that could take longer than 60µs), then precautions must be taken to make sure the data is valid.




Figure 2. Reading the clock registers using the UIP bit.

Another method of reading the registers uses the UIP bit and the transfer-enable (TE) bit. The TE bit, when set to 0, stops transfers between the internal counters and the user registers. Since the last transfer could be corrupted by the write to the TE bit, the UIP bit should be used to verify that an update will not occur when the TE bit is written. Once TE is set to 0, the data may be read from the registers. Since updates are inhibited, it does not matter if the UIP bit is set, or how long it takes to read the registers. This routine could be used instead of the previous one in applications where it may take longer than 60µs to read all the registers.

Once the data are read, the TE bit should be written to 1, enabling transfers. Note that the transfers must be enabled for at least 244µs for a transfer to occur. Because of this requirement, reading sequential values of the subseconds0 registers using this method is impossible (**Figure 3**).




Figure 3. Reading the clock registers using the UIP and TE bits.

The periodic interrupt is synchronized with the update of the clock registers. If the PF flag is used with the interrupt output, the clock registers can be read immediately after an update. If the subseconds registers are being read, the next update will not occur for approximately 244µs. If only the seconds registers are being used, the next update will occur in one second. This routine could be used in applications where periodic updates of the time and date, i.e., for time and date display, are needed. Using the PF flag to drive the interrupt input on a microcontroller allows the system to perform other functions until the time value changes.




Figure 4. Reading the clock registers using the periodic interrupt flag.




Figure 5. Writing the clock registers using the TE and UIP bits.

When writing data to the counter registers, the TE bit can be used. When TE is written to 1, the data written to all the user registers will be transferred to the internal counters. If all the registers are written, no special precautions are necessary. If only some of the registers are written, the issues associated with reading the registers and getting valid data apply regarding the remaining registers. In this case, the UIP bit should be used to avoid a collision.

Related Parts

[DS1318](#)

Parallel-Interface Elapsed Time Counter

[Free Samples](#)

More Information

For Technical Support: <http://www.maximintegrated.com/support>
For Samples: <http://www.maximintegrated.com/samples>
Other Questions and Comments: <http://www.maximintegrated.com/contact>

Application Note 2740: <http://www.maximintegrated.com/an2740>
APPLICATION NOTE 2740, AN2740, AN 2740, APP2740, Appnote2740, Appnote 2740
Copyright © by Maxim Integrated Products
Additional Legal Notices: <http://www.maximintegrated.com/legal>