



Update Notification

Document # : PD22094X5

Issue Date: 15 June 2018

Title of Change:	Update to PD22094X and PD22094X3 announcing the reactivation of previously discontinued parts
Last Time Buy Date:	NA
Last Ship Date:	NA
Contact information:	Contact your local ON Semiconductor Sales Office or <PCN.Support@onsemi.com >
Type of notification:	ON Semiconductor will consider this change accepted, unless an inquiry is made in writing within 30 days of delivery of this notice. To do so, contact <PCN.Support@onsemi.com>.

Description and Purpose:

This is to formally inform customers of the reactivation of devices below that were previously discontinued in PD22094X and PD22094X3. Parts are no longer being discontinued and shall be considered active.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel (tom.siegel@onsemi.com)

☎ +1 765 868 5022

USA

Japan:

Isao Usuki (isao.usuki@onsemi.com)

☎ +81 3 5817 1060

Japan

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

☎ +421 33790 2229

Slovakia

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

☎ +852 2689 0209

China

List of affected Standard Parts

Parts that were previously discontinued in PD22094X		
LA6583MC-AH	LB11867FV-TLM-E	LB1838M-TLM-E
LA6584M-TLM-E	LB11867FV-TLM-H	LB1863M-TLM-E
LA6585FA-BH	LB11867RV-TLM-E	LB1863M-TLM-H
LA6585MC-AH	LB11867RV-TLM-H	LB1868M-TLM-E
LA6588MC-AH	LB11868V-TLM-H	LB1868M-TLM-H
LB11620T-TLM-E	LB11923V-TLM-E	LB8503V-TLM-E
LB11660FV-TLM-E	LB11961-TLM-E	LV8711TL-TLM-H
LB11660FV-TLM-H	LB11961-TLM-H	LV8732VL-TLM-H
LB11660RV-TLM-E	LB11961V-TLM-E	LV8732V-TLM-H
LB11660RV-TLM-H	LB11967V-TLM-H	LV8734VL-TLM-H
LB11685AV-TLM-H	LB11970FV-TLM-H	LV8734V-TLM-H
LB11696V-TLM-E	LB1668M-TLM-E	LV8735V-TLM-H
LB11850VA-TLM-E	LB1668M-TLM-H	LV8736V-TLM-H
LB11850VA-TLM-H	LB1836ML-TLM-E	LV8804FV-TRM-H
Parts that were previously discontinued in PD22094X3		
LB11967V-TLM-E		LB1848MC-BH

NOTE:

Please be informed that there are Customer Specific parts impacted by this notice, thus MPN & CPN info will not be reflected in the parts list of this Generic document. Instead please click the link to the addendum copy provided in the email notification to see full list of affected products specific to your company.

Appendix A: Changed Products

Product	Customer Part Number	Replacement Parts	Replacement Suppliers
LA6583MC-AH		NA	NA
LA6584M-TLM-E		NA	NA
LA6585FA-BH		NA	NA
LA6585MC-AH		NA	NA
LA6588MC-AH		NA	NA
LB11620T-TLM-E		NA	NA
LB11660FV-TLM-E		NA	NA
LB11660FV-TLM-H		NA	NA
LB11660RV-TLM-E		NA	NA
LB11660RV-TLM-H		NA	NA
LB11685AV-TLM-H		NA	NA
LB11696V-TLM-E		NA	NA
LB11850VA-TLM-E		NA	NA
LB11850VA-TLM-H		NA	NA
LB11867FV-TLM-E		NA	NA
LB11867FV-TLM-H		NA	NA
LB11867RV-TLM-E		NA	NA
LB11867RV-TLM-H		NA	NA
LB11868V-TLM-H		NA	NA
LB11923V-TLM-E		NA	NA
LB11961-TLM-E		NA	NA
LB11961-TLM-H		NA	NA



LB11961V-TLM-E		NA	NA
LB11967V-TLM-E		NA	NA
LB11967V-TLM-H		NA	NA
LB11970FV-TLM-H		NA	NA
LB1668M-TLM-E		NA	NA
LB1668M-TLM-H		NA	NA
LB1836ML-TLM-E		NA	NA
LB1838M-TLM-E		NA	NA
LB1848MC-BH		NA	NA
LB1863M-TLM-E		NA	NA
LB1863M-TLM-H		NA	NA
LB1868M-TLM-E		NA	NA
LB1868M-TLM-H		NA	NA
LB8503V-TLM-E		NA	NA
LV8711TL-TLM-H		NA	NA
LV8732V-TLM-H		NA	NA
LV8732VL-TLM-H		NA	NA
LV8734V-TLM-H		NA	NA
LV8734VL-TLM-H		NA	NA
LV8735V-TLM-H		NA	NA
LV8736V-TLM-H		NA	NA
LV8804FV-TRM-H		NA	NA