



THE POWER OF **CONNECTED**

Honeywell Aerospace
12001 State Highway 55
Plymouth, MN 55441

October 12, 2021

Subject: Production hold on HMC1053 Magnetic Sensors

Dear Valued Honeywell Customer:

Honeywell regrets to inform you that a production hold has been placed on HMC1053 magnetic sensors product, due to supply chain challenges. Honeywell will not be able to support any further orders for this part, until further notice.

For any technical support, customers may reach out to PlymouthSupport@Honeywell.com.

If you require further information regarding this notice, please contact Customer Business Manager, Kim Olson at Kim.Olson@Honeywell.com.

We value your feedback, and would be happy to discuss any related issues over the phone. Thank you for your consideration.

Best Regards,

Jeevish G Gurumoorthi
Honeywell Aerospace
Offering Manager (Navigation & Sensors)
Magnetic Sensors - Product Lead
JeevishGlastine.Gurumoorthi@Honeywell.com