



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000995I

DATE: 21-May-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	MAX1791EUB-T	MAX1791EUB+T	16-May-2021	12-Nov-2021	Part is leaded. Request information on lead-free version
Discontinuance	MAX17043G-E+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX1718EEI+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX5975BETE+T	N/A	19-Aug-2020	17-Nov-2020	Part can no longer be manufactured
Discontinuance	MAX5975CETE+	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX5975CETE+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX5975DETE+	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX5975DETE+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX5983BETE+	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX5983BETE+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX767EAP+T	N/A	16-May-2021	12-Nov-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Jun-2020