
End Of Life Notification EOL18.020

This End of Life Notification (EOL) concerns Finisar's 10G CPRI Wireless (1.4km) SFP transceiver, FTLX1370W3BTL and its variants.

Affected Part Numbers and Recommended Replacement Part Numbers

The table below shows part numbers (P/N) affected by this EOL notice, along with the new recommended replacement P/Ns:

EOL P/Ns	Replacement P/Ns
FTLX1370W3BTL	FTLX1370W4BTL
FTLX1370W3BTL-xx	FTLX1370W4BTL-xx
FTLX1370W3BTLxxx	FTLX1370W4BTLxxx

Note: where xx may denote custom parts for various customers

Reason for the EOL notice

The proposed replacement uses an improved FP laser (FP12), ICs and an updated circuitry design which enables Finisar to offer the highest performance products while maintaining competitiveness in the 10G SFP marketplace.

Samples of the new FTLX1370W4BTL platform are available for qualification

Description of the Replacement

The FTLX1370W4BTL is a new generation 10G CPRI wireless SFP transceiver. The Table below shows its main differences over the FTLX1370W3BTL:

Component	1370W3	1370W4
PCB	External source 2(Multek & SSCI)	External source 1(SCC)
Micro Controller	Finisar's (SmartLDPA)	NA
EEPROM	External source 1	External source 1(MACOM)
Laser Driver	Finisar's (SmartLDPA)	External source 1(MACOM)
Post Amplifier	Finisar's (SmartLDPA)	External source 1(MACOM)
Receiver PD	Finisar's (IGP11)	Finisar's (IGP11)
ROSA	Internally Built	Internally Built
Laser Chip	Finisar's (FP11)	Finisar's (FP12)
TOSA	Internally Built	Internally Built and External source 1(YSOD)

End of Life Dates

All last time buy purchase orders must be received by September 20th, 2018. The last time ship date will be December 20th, 2018, or earlier.

Order Acceptance/Change Conditions

Any orders for the discontinued products listed above with a requested ship date after August 20th, 2018 will be non-cancelable and non-returnable (NCNR). The words “non-cancelable, non-returnable” must be clearly indicated on these orders. These orders cannot be changed, rescheduled, or cancelled.

RMA Replacements

After September 20th, 2018, Finisar reserves the right to replace any of the discontinued FTLX1370W3BTL products listed above returned under RMA (Return Material Authorization) with the equivalent FTLX1370W4BTL parts, or with a credit, if it is deemed to be Finisar responsibility.

List of Supporting Materials

Reports concerning reliability and production verification tests for the replacement products FTLX1370W4BTL are available upon request.

For more information

Please do not hesitate to contact your local distributor, representative, or Finisar sales manager for any additional information you need:

Finisar Corporation
1389 Moffett Park Drive
Sunnyvale, CA 94089-1133
Tel. (408) 548-1000 / Fax (408) 541-6138
sales@finisar.com
www.finisar.com