

PRODUCT DISCONTINUATION NOTICE

PDN No.: 2014/003

Affected part numbers	IXYS code nb
MIAA10WB600TMH	502907
MIAA10WD600TMH	502221
MIAA10WE600TMH	502900
MIAA10WF600TMH	504694
MIAA15WB600TMH	503757
MIAA15WD600TMH	504869
MIAA15WE600TMH	504701
MIAA20WB600TMH	503764
MIAA20WD600TMH	504975
MIAA20WE600TMH	504708
MITA10WB1200TMH	502214
MITA15WB1200TMH	505110
MITA30WB600TMH	505721
MITB10WB1200TMH	502722
MITB15WB1200TMH	502893
MIXA100PF1200TMH	511931
MIXA10W1200TMH	509381
MIXA10WB1200TMH	508609
MIXA20W1200TMH	509388
MIXA20WB1200TMH	508616
MIXA30W1200TMH	470414
MIXA40W1200TMH	509395