

PRODUCT DISCONTINUATION



PD_128_15

Reason: End of live Products / Capacity limitation and NO further mass production after CY2016 possible

■ Last order:	2016-06-30
■ Last delivery:	2016-12-31

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
BSN011NE2LS	SP001074736	BSN011NE2LSXUSA1	LG-USON-6			on request	
BSN011NE2LSI	SP001074738	BSN011NE2LSIXUSA1	LG-USON-6			on request	
BSN012N03LS	SP001074740	BSN012N03LSXUSA1	LG-USON-6			on request	
BSN012N03LSI	SP001074742	BSN012N03LSIXUSA1	LG-USON-6			on request	
BSN045NE2LS	SP001074744	BSN045NE2LSXUSA1	LG-USON-6			on request	
BSN048N03LS	SP001074746	BSN048N03LSXUSA1	LG-USON-6			on request	
TDA21310	SP000931598	TDA21310XUSA1	LG-UIQFN-32			on request	

Important Note:

Infineon will assist all customers as much as possible in switching platforms to alternate products to meet customer designs with required layout modification. Please contact your local sales counterpart.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!