


Not For New Design OS-NFND-2022-012

03 October 2022

Expected discontinuation date:	11/1/2022
Reason:	The following products have reached their end of life.
OSRAM OS Expectations:	Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions. Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products. Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.



Please direct your feedback to your local Sales office.

Expected discontinuation date:	11/1/2022
Reason:	The following products have reached their end of life.

Not for new design products				Recommended Replacement		
Device	Ordering Code	Brand	Expected PDN start	Device	Datasheet Ordering Code	Brand
SU CULBN1.VC	Q65113A2463	OSLON UV 3636	11/1/2022	SU CULBN2.VC	Q65113A4848	OSLON UV 3535
SU CULBN1.VC	Q65113A2366	OSLON UV 3636	11/1/2022	SU CULBN2.VC	Q65113A4848	OSLON UV 3535
SU CULDN1.VC	Q65113A2462	OSLON UV 3636	11/1/2022	SU CULDP1.VC	Q65113A4410	OSLON UV 3535
SU CULDN1.VC	Q65113A2365	OSLON UV 3636	11/1/2022	SU CULDP1.VC	Q65113A4410	OSLON UV 3535

Ordering Code Notification	Device	Product Descr.	Brand	Exp. PDN Date	Repl. Product Descr.	Repl. Ordering Code
Q65113A2365	NFND-2022-012 SU	CULDN1.VC SU CULDN1.VC-MAMP-67-4E4F-350-R18	OSLON	11/1/2022	SU CULDP1.VC-MBMD-57-1-185-R18	Q65113A4410
Q65113A2366	NFND-2022-012 SU	CULBN1.VC SU CULBN1.VC-AGAY-67-4F4G-30-R18	OSLON	11/1/2022	SU CULBN2.VC-AGAM-67-4F4G-30-R18	Q65113A4848
Q65113A2462	NFND-2022-012 SU	CULDN1.VC SU CULDN1.VC-MAMF-67-4E4F-350-R18	OSLON	11/1/2022	SU CULDP1.VC-MBMD-57-1-185-R18	Q65113A4410
Q65113A2463	NFND-2022-012 SU	CULBN1.VC SU CULBN1.VC-AGAM-67-4F4G-30-R18	OSLON	11/1/2022	SU CULBN2.VC-AGAM-67-4F4G-30-R18	Q65113A4848