

PRODUCT CHANGE NOTIFICATION

Product Category SMARTZONE SOFTWARE

20200727

Product Group SOFTWARE AND SERVICES

ISSUE DATE: 7/27/2020

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Discontinuation of SynapSense PressureNode 2 (99-0331-001).
 Replace 99-0331-001 in customer orders with SynapSense PressureNode 3 (99-1532-001).
 Pressure Node 3 works with SynapSoft version 7.4.1 and higher. A software upgrade may be required.

Photos/Drawing (where applicable)
 See data sheet: D-PVSP148--WW-ENG-SynapSense Wireless Mesh Pressure Node 3

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2020	7	27
Old product discontinuation date*	2020	7	24

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s) Type Replacement Part 1
 99-0331-001 Direct Replacement 99-1532-001