

Product Discontinuation



PD_089_16

■ Last Order Date:	2017-03-30
■ Last Delivery Date:	2017-09-30

Reason: Discontinuation of specific products in TSSOP-38 package

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
TDA5250	SP000012956	TDA5250XUMA1	PG-TSSOP-38-1			none	
TDA5251	SP000014554	TDA5251XUMA1	PG-TSSOP-38-1			none	
TDA5252	SP000057332	TDA5252XUMA1	PG-TSSOP-38-1			none	
TDA5255	SP000014555	TDA5255XUMA1	PG-TSSOP-38-1			none	
PMA5105	SP000463432	PMA5105XUMA1	PG-TSSOP-38-4			none	
PMA5110	SP000373573	PMA5110XUMA1	PG-TSSOP-38-4			none	
PMA7105	SP000450408	PMA7105XUMA1	PG-TSSOP-38-4			none	
PMA7106	SP000450410	PMA7106XUMA1	PG-TSSOP-38-4			none	
PMA7107	SP000450412	PMA7107XUMA1	PG-TSSOP-38-4			none	
PMA7110	SP000430596	PMA7110XUMA1	PG-TSSOP-38-4			none	

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!