

## Product Discontinuing Notification

<b>1. PDN No.:</b>	<b>PDN18004-1</b>
<b>2. To:</b>	All involved customer
<b>3. Contact Team:</b>	QRA Sunnie Lin PM Chris Lin
<b>4. Issue date:</b>	2018/7/5
<b>5. Affected product/ product family:</b>	<b>6. Recommended replacement:</b>
BAT42 (-L0) HF & Non-HF BAT43 (-L0) HF & Non-HF BAS85 (-L0) HF & Non-HF  See attached detailed Part-No. list.	See attached detailed Part-No. list.
<b>7. Reason for discontinuing:</b>	
Manufacturability issue due to environmental constrain	
<b>8. Last time buy/ order entry:</b>	2018/7/31
<b>9. Last shipment date:</b>	2018/12/31
<b>10. Please let us know if you have any question/ comment:</b>	
N/A	
<b>11. Customer feedback required latest:</b> <b>(should we receive no feedback, the change will be deemed as accepted!)</b>	2018/8/20
<b>12. Approved by:</b>	Lloyd Sebial Opolentisima

Family	Package	TSC P/N	New TSC P/N
Schottky	DO-35	BAT42 A0	None
Schottky	DO-35	BAT42 A0G	None
Schottky	DO-35	BAT42 R0	None
Schottky	DO-35	BAT42 R0G	None
Schottky	DO-35	BAT42-L0 A0	None
Schottky	DO-35	BAT42-L0 A0G	None
Schottky	DO-35	BAT42-L0 R0	None
Schottky	DO-35	BAT42-L0 R0G	None
Schottky	DO-35	BAT43 A0	None
Schottky	DO-35	BAT43 A0G	None
Schottky	DO-35	BAT43 R0	None
Schottky	DO-35	BAT43 R0G	None
Schottky	DO-35	BAT43-L0 A0	None
Schottky	DO-35	BAT43-L0 A0G	None
Schottky	DO-35	BAT43-L0 R0	None
Schottky	DO-35	BAT43-L0 R0G	None
Schottky	MMELF	BAS85 L0	None
Schottky	MMELF	BAS85 L0G	None
Schottky	MMELF	BAS85 L1	None
Schottky	MMELF	BAS85 L1G	None
Schottky	MMELF	BAS85-L0 L0	None
Schottky	MMELF	BAS85-L0 L0G	None
Schottky	MMELF	BAS85-L0 L1	None
Schottky	MMELF	BAS85-L0 L1G	None