



Premstaetten, September 19, 2018

PCN31-2018 (CMV50K Assembly process update)

Dear Customer,

In order to ensure the continuous improvement we have changed our bonding assembly process at our supplier and migrated to a “Ball Stitch On Ball” process (BSOB).

With this update, ams has the clear objective to create a more robust, efficient and quality driven CMV50K supply chain, supporting all customers forecast demands.

Affected products:

<u>material ID</u>	<u>product description</u>
302390003	CMV50000-1E3M1PA QA
302860003	CMV50000-1E3C1PA QA

Impact on product performance

This change has no impact on the characteristics of the product performance.

Impact on reliability/qualification status

A qualification program has been completed successfully to qualify the change.

Timing of change

ams will introduce the BSOB immediately into the supply chain.

Please be advised that unless we receive your written refusal concerning this PCN within 30 days, the PCN shall be deemed accepted.

Best regards,

A handwritten signature in black ink, appearing to read 'M. Pflieger'.

Michael Pflieger

ams AG

Director Operations ISS