

Product Change Notice

Issue Date: 15 Oct 2019**Change Type:**

New zener and dice source for the part numbers listed below.

Parts Affected:

ASMP-CWH1-ZCEB2	ASMP-CWH1-ZDFH2	ASMP-CWH1-ZDFD2
ASMP-CWH1-ZBE02	ASMP-CWH0-ZDFH2	ASMP-CWH1-ZDFE2
ASMP-CWH1-ZBE12	ASMP-CWH0-ZDF12	ASMP-CWH1-ZDFF2
ASMP-CWH0-ZCF02	ASMP-CWH0-ZDFA2	QSMP-CWCN-ZDEA2
ASMP-CWH0-ZDFF2	ASMP-CWH0-ZDFG2	QSMP-CWPM-ZDEZ2
ASMP-CWH0-ZDFE2	ASMP-CWH0-ZDFJ2	QSMP-CWP2-ZDFZ2
ASMP-CWH0-ZDFD2	ASMP-CWH1-ZDF02	QSMP-CWPM-ZDEC2
ASMP-CWH0-ZDFC2	ASMP-CWH1-ZDF12	QSMP-CWH1-ZCEB2
ASMP-CWH0-ZDFB2	ASMP-CWH1-ZDFA2	QSMP-CWJK-ZCEC2
ASMP-CWH1-ZDFJ2	ASMP-CWH1-ZDFB2	QSMP-CWFN-ZBDZ2
ASMP-CWH1-ZDFG2	ASMP-CWH1-ZDFC2	QSMP-CWSB-ZDFB2

Description and Extent of Change:

The new zener and dice shall be replacing the current zener and dice for the part numbers listed above.

Reasons for Change:

Assurance of supply.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There will be no change on fit, form, function, quality and reliability of final product.

Effective Date of Change:

The shipment with above change will commence 90 days after issuance date above.

Qualification Data:

No change in reliability performance. Product characterization data will be available upon request.

These changes have been reviewed and approved by Broadcom engineers and managers per Broadcom' procedure: Change Control and Customer Notification, 5962-6052-80.

Please contact your Broadcom field sales for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.