

Product Advisory

Issue Date: 8-December-2022

Change Description:

Adhesive material using to attach lid to substrate, Loctite AA01 supply discontinuity. Phase in new adhesive material Loctite CE3920.

Parts Affected:

SS14-0B00-00
SS15-0B00-00
SS16-0B00-00
SS17-0B00-00
SS18-0B00-00
SS19-0B00-00
PEX8714-AB80BI G
PEX8718-AB80BI G
PEX8734-AB80BI G
PEX8750-AB80BI G
PEX8764-AB80BI G
PEX8780-AB80BI G
PEX8796-AB80BI G
PEX8796-AB80BIGX
PEX8712-CA80BC G
PEX8713-CA80BC G
PEX8716-CA80BC G
PEX8717-CA80BC G
PEX8723-CA80BC G
PEX8724-CA80BC G
PEX8725-CA80BC G
PEX8732-CA80BC G
PEX8733-CA80BC G
PEX8747-CA80BC G
PEX8747-CA80FBC G
PEX8748-CA80BC G
PEX8749-CA80BC G

Description and Extent of Change:

Adhesive material to attach lid to substrate, Loctite AA01 is been discontinue.
Qualified adhesive material Loctite CE3920 will be phase in immediately to support demand.

Reasons for Change:

Supplier discontinuity, transition to alternate adhesive material immediately to ensure uninterrupted supply.



Effect of Change on Fit, Form, Function, Quality, or Reliability:

The device specification will remain the same, which will ensure product performance per datasheet.

Effective Date of Change:

Product shipments using this change will begin after 7-January-2023. Timing of shipment of the changed part will vary by part number depending on qualification completion, customer demand, and inventory levels.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.