

Product Discontinuation Notice

February 2012

Discontinuation of TN Relays



1. Reason: Replacement part

2. Affected parts:

TN relays 	All types	TN2-
---	-----------	------

3. Last time buy: End of August 2013

4. Substitution:

GN (AGN) relays (The terminal pitch is different.)	AGN2O
---	-------

Any questions, please contact your local Panasonic Electric Works Sales representatives.

(Ref#: T-1246-03)

Affected Parts List

TN2-12V
TN2-12V-3
TN2-24V
TN2-24V-3
TN2-3V
TN2-3V-3
TN2-4.5V
TN2-4.5V-3
TN2-48V
TN2-48V-3
TN2-5V
TN2-5V-3
TN2-6V
TN2-6V-3
TN2-9V
TN2-9V-3
TN2-H-12V
TN2-H-12V-3
TN2-H-24V
TN2-H-24V-3
TN2-H-3V
TN2-H-3V-3
TN2-H-4.5V
TN2-H-4.5V-3
TN2-H-48V
TN2-H-48V-3
TN2-H-5V
TN2-H-5V-3
TN2-H-6V
TN2-H-6V-3
TN2-H-9V
TN2-H-9V-3
TN2-L-12V
TN2-L-12V-3
TN2-L2-12V
TN2-L2-12V-3
TN2-L2-24V
TN2-L2-24V-3
TN2-L2-3V
TN2-L2-3V-3
TN2-L2-4.5V
TN2-L2-4.5V-3
TN2-L-24V
TN2-L-24V-3
TN2-L2-5V

TN2-L2-5V-3
TN2-L2-6V
TN2-L2-6V-3
TN2-L2-9V
TN2-L2-9V-3
TN2-L2-H-12V
TN2-L2-H-12V-3
TN2-L2-H-24V
TN2-L2-H-24V-3
TN2-L2-H-3V
TN2-L2-H-3V-3
TN2-L2-H-4.5V
TN2-L2-H-4.5V-3
TN2-L2-H-5V
TN2-L2-H-5V-3
TN2-L2-H-6V
TN2-L2-H-6V-3
TN2-L2-H-9V
TN2-L2-H-9V-3
TN2-L-3V
TN2-L-3V-3
TN2-L-4.5V
TN2-L-4.5V-3
TN2-L-5V
TN2-L-5V-3
TN2-L-6V
TN2-L-6V-3
TN2-L-9V
TN2-L-9V-3
TN2-L-H-12V
TN2-L-H-12V-3
TN2-L-H-24V
TN2-L-H-24V-3
TN2-L-H-3V
TN2-L-H-3V-3
TN2-L-H-4.5V
TN2-L-H-4.5V-3
TN2-L-H-5V
TN2-L-H-5V-3
TN2-L-H-6V
TN2-L-H-6V-3
TN2-L-H-9V
TN2-L-H-9V-3