



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000983N

DATE: 31-Jan-2020

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	VT1316MAFQ-051	N/A	30-Jan-2021	29-Jul-2021	Part can no longer be manufactured
Lead-Free Conversion	VT1316MAFQ-052	N/A	30-Jan-2021	29-Jul-2021	Part can no longer be manufactured
Lead-Free Conversion	VT1316MAFQX-051	N/A	30-Jan-2021	29-Jul-2021	Part can no longer be manufactured
Discontinuance	MAXQ612X-2031+	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ612X-2032+	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ612X-2051+	N/A	30-Jan-2021	29-Jul-2021	Part can no longer be manufactured
Discontinuance	MAXQ612X-2543+	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ612X-2595+	N/A	30-Jan-2021	29-Jul-2021	Part can no longer be manufactured
Discontinuance	MAXQ612X-2603+	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ613X-2607+	N/A	30-Jan-2021	29-Jul-2021	Part can no longer be manufactured
Discontinuance	MAXQ613X-2608+	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ613X-2609+	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ613X-UEI+	N/A	30-Jan-2021	29-Jul-2021	Part can no longer be manufactured
Discontinuance	VT1300MFQ	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1300MFQX	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1311MFQ	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1311MFQX	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1315MFQ	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1315MFQX	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1316MAFQ-031	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1316MAFQ-041	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1316MAFQX-031	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1316MAFQX-052	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1318MFQ	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1556MFQ	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1556MFQX	N/A	30-Jan-2021	29-Jul-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Mar-2020

Discontinuance	VT256FC-ADJ	N/A	30-Jan-2021	29-Jul-2021	Part can no longer be manufactured
Discontinuance	VT256FCX-ADJ	N/A	30-Jan-2021	29-Jul-2021	Part can no longer be manufactured
Discontinuance	VT545WFQ	N/A	30-Jan-2021	30-Jan-2021	Part can no longer be manufactured