


Light is OSRAM

Product Or Individual Q-Code Discontinuation (acc. JEDEC J-STD-048)
OS-PDN-2019-020

15 July 2019

Last order: 15 January 2020
Last delivery: 15 December 2020



Please direct your feedback to your local Sales office.

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
LE UW Q9WP	all					
LE UW Q9WP-N68N-HM-0-A40-R18B-Z-AL	Q65111A2572	OSRAM OSTAR	No sufficient future volume forecast	KW CELNM1.TG-Z5NF6-ebvFfcbB46-15B3-A-S	Q65112A1576	OSLON
LE UW Q9WP-8M7N-GMKM-0-A40-R18-Z	Q65110A9235	OSRAM OSTAR	No sufficient future volume forecast	KW CELNM1.TG-Z5NF6-ebvFfcbB46-15B3-A-S	Q65112A1576	OSLON
LE UW Q9WP-5N8N-HM-0-A40-R18B-Z-XX	Q65111A2574	OSRAM OSTAR	No sufficient future volume forecast	KW CELNM1.TG-Z5NF6-ebvFfcbB46-15B3-A-S	Q65112A1576	OSLON
LE UW Q9WP-5N8N-HM-0-A40-R18B-Z-AL	Q65111A2575	OSRAM OSTAR	No sufficient future volume forecast	KW CELNM1.TG-Z5NF6-ebvFfcbB46-15B3-A-S	Q65112A1576	OSLON
LE UW D1W5 01	all					
LE UW D1W5 01-7P8Q-GMKM-T01	Q65110A8589	OSRAM OSTAR	No sufficient future volume forecast	KW HLL531.TE-Z7R9-ebvFfcbB46-RS5R-A00-S	Q65112A8171	OSLON
LE UW D1W5 01-6Q6R-IM-T10-ZKW	Q65111A0729	OSRAM OSTAR	No sufficient future volume forecast	KW HLL531.TE-Z7R9-ebvFfcbB46-RS5R-A00-S	Q65112A8171	OSLON
LE UW D1W5 01-6Q6R-IM-T10-XX	Q65111A5868	OSRAM OSTAR	No sufficient future volume forecast	KW HLL531.TE-Z7R9-ebvFfcbB46-RS5R-A00-S	Q65112A8171	OSLON
LE UW D1W5 01-5Q6R-IM-T10-ZKW	Q65111A0123	OSRAM OSTAR	No sufficient future volume forecast	KW HLL531.TE-Z7R9-ebvFfcbB46-RS5R-A00-S	Q65112A8171	OSLON
LE UW D1W4 01	all					
LE UW D1W4 01-8P8Q-IM-T10-ZKW	Q65111A0471	OSRAM OSTAR	No sufficient future volume forecast	KW HKL531.TE-Z5RF7-ebvFfcbB46-4LZL-A00-S	Q65112A8170	OSLON
LE UW D1W4 01-7P5Q-IM-T10-HE	Q65110A8565	OSRAM OSTAR	No sufficient future volume forecast	KW HKL531.TE-Z5RF7-ebvFfcbB46-4LZL-A00-S	Q65112A8170	OSLON
LE UW D1W4 01-5P6Q-GMKM-T01	Q65110A8593	OSRAM OSTAR	No sufficient future volume forecast	KW HKL531.TE-Z5RF7-ebvFfcbB46-4LZL-A00-S	Q65112A8170	OSLON
LE UW D1W3 03	all					
LE UW D1W3 03-N58P-HMIM-T05-V-AL	Q65111A0690	OSRAM OSTAR	No sufficient future volume forecast	KW HJL531.TE-Z7Q7-ebvFfcbB46-DFYF-A00-S	Q65112A8169	OSLON
LE UW D1W3 03-N58P-GM-T05-AL	Q65110A9342	OSRAM OSTAR	No sufficient future volume forecast	KW HJL531.TE-Z7Q7-ebvFfcbB46-DFYF-A00-S	Q65112A8169	OSLON
LE UW D1W3 02	all					
LE UW D1W3 02-N57P-I3-T01-HE	Q65110A8572	OSRAM OSTAR	No sufficient future volume forecast	KW HJL531.TE-Z7Q7-ebvFfcbB46-DFYF-A00-S	Q65112A8169	OSLON

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
LE UW D1W3 01	all					
LE UW D1W3 01-7N7P-GMKM-T01	Q65110A8588	OSRAM OSTAR	No sufficient future volume forecast	KW HJL531.TE-Z7Q7- ebvFfcbB46-DFYF-A00-S	Q65112A8169	OSLON
LE UW D1W3 01-5P8P-IM-T10-ZKW	Q65111A2001	OSRAM OSTAR	No sufficient future volume forecast	KW HJL531.TE-Z7Q7- ebvFfcbB46-DFYF-A00-S	Q65112A8169	OSLON
LE UW D1W3 01-5P8P-IM-T10-HE	Q65111A0570	OSRAM OSTAR	No sufficient future volume forecast	KW HJL531.TE-Z7Q7- ebvFfcbB46-DFYF-A00-S	Q65112A8169	OSLON
LE UW D1W3 01-5P7P-JM-T01-VAR	Q65111A1793	OSRAM OSTAR	No sufficient future volume forecast	KW HJL531.TE-Z7Q7- ebvFfcbB46-DFYF-A00-S	Q65112A8169	OSLON
LE UW D1W2 01	all					
LE UW D1W2 01-7M7N-GMKM-T01	Q65110A8590	OSRAM OSTAR	No sufficient future volume forecast	KW2 HIL532.TK-D2D9- 4L06M0-SC6B-S	Q65112A8069	OSLON
LE UW D1W2 01-5N7N-IM-T10-HE	Q65110A8567	OSRAM OSTAR	No sufficient future volume forecast	KW2 HIL532.TK-D2D9- 4L06M0-SC6B-S	Q65112A8069	OSLON
LE UW D1W2 01-5N5P-KM-T10-VAR	Q65110A9709	OSRAM OSTAR	No sufficient future volume forecast	KW2 HIL532.TK-D2D9- 4L06M0-SC6B-S	Q65112A8069	OSLON
LE UW D1W1 01	all					
LE UW D1W1 01-7L5M-IM-T10-HE	Q65110A8566	OSRAM OSTAR	No sufficient future volume forecast	KW HHL532.TK-S2S8- 4L06M0-2686-S	Q65112A8068	OSLON
LE UW D1W1 01-5L6M-GMKM-T01	Q65110A8591	OSRAM OSTAR	No sufficient future volume forecast	KW HHL532.TK-S2S8- 4L06M0-2686-S	Q65112A8068	OSLON

Products Affected by Product Discontinuation Notification

Number: OS-PDN-2019-020

Name: Product Discontinuation due to low future forecast and demand

Release Date: 7/15/2019

Last Order: 1/15/2020

Last Delivery: 12/15/2020

DISCONTINUED

NEW (REPLACEMENT)

Product	QNumber	QNumber Description	Part Number	Product	QNumber	QNumber Description	Part Number
LE UW D1W	Q65110A8566	LE UW D1W1 01-7L5M-IM-T10-HE	LE UW D1W1 01-7L5M-IM-T10-HE	KW HHL532.	Q65112A8068	KW HHL532.TK-S2S8-4L06M0-2686-S	
LE UW D1W	Q65110A8591	LE UW D1W1 01-5L6M-GMKM-T01	LE UW D1W1 01-5L6M-GMKM-T01	KW HHL532.	Q65112A8068	KW HHL532.TK-S2S8-4L06M0-2686-S	
LE UW D1W	Q65110A8567	LE UW D1W2 01-5N7N-IM-T10-HE	LE UW D1W2 01-5N7N-IM-HE	KW2 HIL532.	Q65112A8069	KW2 HIL532.TK-D2D9-4L06M0-SC6B-S	
LE UW D1W	Q65110A8590	LE UW D1W2 01-7M7N-GMKM-T01	LE UW D1W2 01-7M7N-GMKM-T01	KW2 HIL532.	Q65112A8069	KW2 HIL532.TK-D2D9-4L06M0-SC6B-S	
LE UW D1W	Q65110A9709	LE UW D1W2 01-5N5P-KM-T10-VAR	LE UW D1W2 01-5N5P-KM-VAR	KW2 HIL532.	Q65112A8069	KW2 HIL532.TK-D2D9-4L06M0-SC6B-S	
LE UW D1W	Q65110A8588	LE UW D1W3 01-7N7P-GMKM-T01	LE UW D1W3 01-7N7P-GMKM-T01	KW HJL531.	Q65112A8169	KW HJL531.TE-Z7Q7-ebvFfcbB46-DFYF-A00-	
LE UW D1W	Q65111A0570	LE UW D1W3 01-5P8P-IM-T10-HE	LE UW D1W3 01-5P8P-IM-HE	KW HJL531.	Q65112A8169	KW HJL531.TE-Z7Q7-ebvFfcbB46-DFYF-A00-	
LE UW D1W	Q65111A1793	LE UW D1W3 01-5P7P-JM-T01-VAR	LE UW D1W3 01-5P7P-JM-VAR	KW HJL531.	Q65112A8169	KW HJL531.TE-Z7Q7-ebvFfcbB46-DFYF-A00-	
LE UW D1W	Q65111A2001	LE UW D1W3 01-5P8P-IM-T10-ZKW	LE UW D1W3 01-5P8P-IM-T10-ZKW	KW HJL531.	Q65112A8169	KW HJL531.TE-Z7Q7-ebvFfcbB46-DFYF-A00-	
LE UW D1W	Q65110A8572	LE UW D1W3 02-N57P-I3-T01-HE	LE UW D1W3 02-N57P-I3-T01-HE	KW HJL531.	Q65112A8169	KW HJL531.TE-Z7Q7-ebvFfcbB46-DFYF-A00-	
LE UW D1W	Q65110A9342	LE UW D1W3 03-N58P-GM-T05-AL	LE UW D1W3 03-N58P-GM-T05-0-AL	KW HJL531.	Q65112A8169	KW HJL531.TE-Z7Q7-ebvFfcbB46-DFYF-A00-	
LE UW D1W	Q65111A0690	LE UW D1W3 03-N58P-HMIM-T05-V-AL	LE UW D1W3 03-N58P-HMIM-V-AL	KW HJL531.	Q65112A8169	KW HJL531.TE-Z7Q7-ebvFfcbB46-DFYF-A00-	
LE UW D1W	Q65110A8565	LE UW D1W4 01-7P5Q-IM-T10-HE	LE UW D1W4 01-7P5Q-IM-T10-HE	KW HKL531.	Q65112A8170	KW HKL531.TE-Z5RF7-ebvFfcbB46-4LZL-A00	
LE UW D1W	Q65110A8593	LE UW D1W4 01-5P6Q-GMKM-T01	LE UW D1W4 01-5P6Q-GMKM-T01	KW HKL531.	Q65112A8170	KW HKL531.TE-Z5RF7-ebvFfcbB46-4LZL-A00	
LE UW D1W	Q65111A0471	LE UW D1W4 01-8P8Q-IM-T10-ZKW	LE UW D1W4 01-8P8Q-IM-T10-ZKW	KW HKL531.	Q65112A8170	KW HKL531.TE-Z5RF7-ebvFfcbB46-4LZL-A00	
LE UW D1W	Q65110A8589	LE UW D1W5 01-7P8Q-GMKM-T01	LE UW D1W5 01-7P8Q-GMKM-T01	KW HLL531.	Q65112A8171	KW HLL531.TE-Z7R9-ebvFfcbB46-RS5R-A00-	
LE UW D1W	Q65111A0123	LE UW D1W5 01-5Q6R-IM-T10-ZKW	LE UW D1W5 01-5Q6R-IM-T10-ZKW	KW HLL531.	Q65112A8171	KW HLL531.TE-Z7R9-ebvFfcbB46-RS5R-A00-	
LE UW D1W	Q65111A0729	LE UW D1W5 01-6Q6R-IM-T10-ZKW	LE UW D1W5 01-6Q6R-IM-T10-ZKW	KW HLL531.	Q65112A8171	KW HLL531.TE-Z7R9-ebvFfcbB46-RS5R-A00-	
LE UW D1W	Q65111A5868	LE UW D1W5 01-6Q6R-IM-T10-XX	LE UW D1W5 01-6Q6R-IM-T10-XX	KW HLL531.	Q65112A8171	KW HLL531.TE-Z7R9-ebvFfcbB46-RS5R-A00-	
LE UW Q9W	Q65110A9235	LE UW Q9WP-8M7N-GMKM-0-A40-R18-Z	LE UW Q9WP-8M7N-GMKM-Z	KW CELNM1	Q65112A1576	KW CELNM1.TG-Z5NF6-ebvFfcbB46-15B3-A-	KW CELNM1.TG-5NF8N-EBVF46FC
LE UW Q9W	Q65111A2572	LE UW Q9WP-N68N-HM-0-A40-R18B-Z-AL	LE UW Q9WP-N68N-HM-L-SB-AL	KW CELNM1	Q65112A1576	KW CELNM1.TG-Z5NF6-ebvFfcbB46-15B3-A-	KW CELNM1.TG-5NF8N-EBVF46FC
LE UW Q9W	Q65111A2574	LE UW Q9WP-5N8N-HM-0-A40-R18B-Z-XX	LE UW Q9WP-5N8N-HM-SB-Z-XX	KW CELNM1	Q65112A1576	KW CELNM1.TG-Z5NF6-ebvFfcbB46-15B3-A-	KW CELNM1.TG-5NF8N-EBVF46FC
LE UW Q9W	Q65111A2575	LE UW Q9WP-5N8N-HM-0-A40-R18B-Z-AL	LE UW Q9WP-5N8N-HM-SB-Z-AL	KW CELNM1	Q65112A1576	KW CELNM1.TG-Z5NF6-ebvFfcbB46-15B3-A-	KW CELNM1.TG-5NF8N-EBVF46FC