



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: 462

DATE: 08-Apr-2008

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	DS2405	N/A	08-Oct-2008	08-Apr-2010	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS2405-037-01	N/A	08-Oct-2008	08-Apr-2010	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS2405/T&R	N/A	08-Oct-2008	08-Apr-2010	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS2405P	N/A	08-Oct-2008	08-Apr-2010	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS2405P/T&R	N/A	08-Oct-2008	08-Apr-2010	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS2405Z	N/A	08-Oct-2008	08-Apr-2010	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS2405Z/T&R	N/A	08-Oct-2008	08-Apr-2010	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS2423P	N/A	08-Oct-2008	08-Apr-2010	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS2423P/T&R	N/A	08-Oct-2008	08-Apr-2010	Part is leaded. Request information on lead-free version
Discontinuance	DS1963L-F5	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS1963L-F5+	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS1963L-F5+W	N/A	08-Oct-2008	08-Apr-2010	The part was not released
Discontinuance	DS1963L-F5X	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405+	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405+T&R	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405-037-01+	N/A	08-Oct-2008	08-Apr-2010	The part was not released
Discontinuance	DS2405AP-02C-	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405AP-02C-114/T&R-	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405AP-02C-166/T&R-	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405AP-02C-	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405AR-100-550/T	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405P+	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405P+T&R	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405P-02C	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405P-02C-114/SANYO	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405P-02C-114/T&R-	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 09-May-2008

Discontinuance	DS2405P-02C-166/T&R-	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405P-02C-166/VARTA	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405P-02C/T&R	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405Z+	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405Z+T&R	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2405Z-02F-4D43+T	N/A	08-Oct-2008	08-Apr-2010	The part was not released
Discontinuance	DS2423P+	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2423P+T&R	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2423P-500-00/T&R	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured
Discontinuance	DS2423X	N/A	08-Oct-2008	08-Apr-2010	Part can no longer be manufactured