


Not For New Design OS-NFND-2022-010

16 August 2022

Expected discontinuation date:	01.11.2022
Reason:	The following products have reached their end of life.
OSRAM OS Expectations:	Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions. Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products. Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.



Please direct your feedback to your local Sales office.

Expected discontinuation date: 01.11.2022

Reason: The following products have reached their end of life.

Not for new design products				Recommended Replacement		
Device	Ordering Code	Brand	Expected PDN start	Device	Datasheet Ordering Code	Brand
GD CSHPM1.14	Q65112A9490	OSLON SSL 150	01.11.2022	NO REPLACEMENT		
GD CSHPM1.14	Q65113A1189	OSLON SSL 150	01.11.2022	NO REPLACEMENT		
GD CSHPM1.14	Q65113A1220	OSLON SSL 150	01.11.2022	NO REPLACEMENT		
GD CSHPM1.14	Q65113A2064	OSLON SSL 150	01.11.2022	NO REPLACEMENT		
GD CSHPM1.14	Q65113A3375	OSLON SSL 150	01.11.2022	NO REPLACEMENT		