

TDK-EPC Corporation's

CERAMIC CAPACITORS

G. M.

Hiroyuki Uemura

Discontinuation Notice of Dip Capacitor (Dipped radial lead type) Y5V Products

First of all, we would like to thank you for your continued patronage of TDK products. The purpose of this letter is to inform you TDK is planning to discontinue the manufacture of the certain capacitor products we are shipping to you.

Due to a consolidation of our ceramic capacitor portfolio, we will discontinue the manufacture of the products listed below by Dec.31.2013, and accept all last time orders by Jun.30.2013. In a sincere attempt to assist our customers, TDK is providing this list of discontinued part numbers with your corresponding part number.

Description

| Your product name | Our product name | Our substitute |
|-------------------|-------------------|----------------|
| FK11Y5V0J107Z | FK11Y5V0J107ZN020 | |
| FK11Y5V1A476Z | FK11Y5V1A476ZN020 | |
| FK11Y5V1C226Z | FK11Y5V1C226ZN020 | |
| FK11Y5V1C476Z | FK11Y5V1C476ZN020 | |
| FK11Y5V1E106Z | FK11Y5V1E106ZN020 | |
| FK11Y5V1E226Z | FK11Y5V1E226ZN020 | |
| FK11Y5V1H106Z | FK11Y5V1H106ZN020 | |
| FK11Y5V1H475Z | FK11Y5V1H475ZN020 | |
| FK14Y5V0J226Z | FK14Y5V0J226ZN020 | |
| FK14Y5V1A106Z | FK14Y5V1A106ZN020 | |
| FK14Y5V1C106Z | FK14Y5V1C106ZN020 | |
| FK14Y5V1C475Z | FK14Y5V1C475ZN020 | |

After receiving this letter, please send an acknowledgement to your local TDK local salesperson by Dec.31.2012. Our salesperson will contact you to discuss the last time order and details.

We apologize for any inconveniences caused by this discontinuation, but we do hope for your kind understanding and your cooperation.

Sincerely yours,

| | |
|--------|------------------|
| Accept | |
| | Company _____ |
| | Department _____ |
| | Name _____ |

TCH/DISTRIBUTOR

| Your product name | Our product name | Our substitute |
|-------------------|-------------------|----------------|
| FK14Y5V1E225Z | FK14Y5V1E225ZN020 | |
| FK14Y5V1E475Z | FK14Y5V1E475ZN020 | |
| FK14Y5V1H105Z | FK14Y5V1H105ZN020 | |
| FK14Y5V1H225Z | FK14Y5V1H225ZN020 | |
| FK14Y5V1H474Z | FK14Y5V1H474ZN020 | |
| FK16Y5V0J476Z | FK16Y5V0J476ZN020 | |
| FK16Y5V1A226Z | FK16Y5V1A226ZN020 | |
| FK16Y5V1C106Z | FK16Y5V1C106ZN020 | |
| FK16Y5V1C226Z | FK16Y5V1C226ZN020 | |
| FK16Y5V1E106Z | FK16Y5V1E106ZN020 | |
| FK16Y5V1E475Z | FK16Y5V1E475ZN020 | |
| FK16Y5V1H225Z | FK16Y5V1H225ZN020 | |
| FK16Y5V1H475Z | FK16Y5V1H475ZN020 | |
| FK18Y5V0J475Z | FK18Y5V0J475ZN020 | |
| FK18Y5V1A225Z | FK18Y5V1A225ZN020 | |
| FK18Y5V1C105Z | FK18Y5V1C105ZN020 | |
| FK18Y5V1C225Z | FK18Y5V1C225ZN020 | |
| FK18Y5V1E105Z | FK18Y5V1E105ZN020 | |
| FK18Y5V1E474Z | FK18Y5V1E474ZN020 | |
| FK18Y5V1H104Z | FK18Y5V1H104ZN020 | |
| FK18Y5V1H224Z | FK18Y5V1H224ZN020 | |
| FK18Y5V1H474Z | FK18Y5V1H474ZN020 | |
| FK20Y5V1A476Z | FK20Y5V1A476ZN000 | |
| FK20Y5V1C226Z | FK20Y5V1C226ZN000 | |
| FK20Y5V1C476Z | FK20Y5V1C476ZN000 | |
| FK20Y5V1E106Z | FK20Y5V1E106ZN000 | |
| FK20Y5V1E226Z | FK20Y5V1E226ZN000 | |
| FK20Y5V1H106Z | FK20Y5V1H106ZN000 | |
| FK20Y5V1H475Z | FK20Y5V1H475ZN000 | |
| FK22Y5V1A107Z | FK22Y5V1A107ZN000 | |
| FK22Y5V1C476Z | FK22Y5V1C476ZN000 | |
| FK22Y5V1E226Z | FK22Y5V1E226ZN000 | |
| FK22Y5V1H106Z | FK22Y5V1H106ZN000 | |
| FK24Y5V0J226Z | FK24Y5V0J226ZR000 | |
| FK24Y5V1A106Z | FK24Y5V1A106ZN000 | |
| FK24Y5V1C106Z | FK24Y5V1C106ZN000 | |
| FK24Y5V1C475Z | FK24Y5V1C475ZN000 | |
| FK24Y5V1E225Z | FK24Y5V1E225ZN000 | |
| FK24Y5V1E475Z | FK24Y5V1E475ZN000 | |
| FK24Y5V1H105Z | FK24Y5V1H105ZN000 | |
| FK24Y5V1H225Z | FK24Y5V1H225ZN000 | |
| FK24Y5V1H474Z | FK24Y5V1H474ZN000 | |
| FK26Y5V0J476Z | FK26Y5V0J476ZN000 | |
| FK26Y5V1A226Z | FK26Y5V1A226ZN000 | |
| FK26Y5V1C106Z | FK26Y5V1C106ZN000 | |
| FK26Y5V1C226Z | FK26Y5V1C226ZN000 | |
| FK26Y5V1E106Z | FK26Y5V1E106ZN000 | |
| FK26Y5V1E475Z | FK26Y5V1E475ZN000 | |

| |
|--|
| Accept |
| <p>_____ Company</p> <p>_____ Department</p> <p>_____ Name</p> |

