



Product Discontinuance Notice

MEMS Oscillator Product Discontinuance Notice (PDN): PDN NC-14-01.

Effective Date: June 20, 2014

IDT is discontinuing its MEMS oscillator product family.

Reason for Discontinuance.

IDT is committed to, and has a solid history of, delivering products of the highest quality and reliability to its customers and of also providing its customers with the maximum amount of notice possible whenever a product must be discontinued. Maintaining such standards is a high priority for IDT, and one from which it does not deviate, except in the most critical of circumstances.

Regrettably, IDT has experienced a manufacturing-related issue with its MEMS oscillator products which, after diligent effort, has not been satisfactorily rectified. Further, we have found that the manifestation of the issue cannot be reliably screened prior to the part's use in the field. Consequently, in order to assure that our customer applications are not put at risk, IDT must discontinue shipment of all MEMS oscillator products, *effective immediately*. Due to this issue, IDT is unable to offer any last-time-buys.

IDT realizes the importance of continued supply and as such, will be available to assist you in identifying functional replacements. The affected parts are listed on the following pages.

If you have any additional questions or concerns related to this PDN, you may contact your local IDT sales office. You can find their contact information by visiting our website at <http://www.idt.com/buy-sample/locations>. If you are unable to contact your local IDT sales office, you may contact IDT marketing using the contact information below.

Sincerely,

Ron Wade

IDT
Technical Marketing Manger
Ron.Wade@idt.com
Phone: +1 (408) 284-6563



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: <u>NC-14-01</u>	Last Buy Deadline for Submission of Order: <u>12-Jul-2014</u>
Issue Date: <u>12-Jul-2014</u>	Last Eligible Ship Date: <u>12-Jul-2014</u>

Contact: Victor Abarca
 E-mail: victor.abarca@idt.com

PRODUCT(S) AFFECTED: **ATTACHMENT** Yes No
(List Replacement Part #(s), if any)

Selective devices as listed in the attachment will be discontinued.

REASON FOR DISCONTINUANCE:

- | | |
|--|---|
| <input type="checkbox"/> Replace slower speed with faster speed offerings
<input type="checkbox"/> Obsolete Fab Technology / Process
<input type="checkbox"/> Obsolete Assembly Technology / Process
<input type="checkbox"/> Obsolete Package / Material
<input type="checkbox"/> Declined Market | <input checked="" type="checkbox"/> Other: <u>Manufacturing discontinuance</u>
<hr/>
<hr/>
<hr/> |
|--|---|

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____	E-Mail Address: _____
Name/Date: _____	Phone#: _____
Title: _____	Fax#: _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGEMENT:

Received By: _____ Date: _____



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group	Remark
4-EVAL-32-00	None	None	N/A	NCM	
4-EVAL-53-00	None	None	N/A	NCM	
4-EVAL-75-00	None	None	N/A	NCM	
4-EVK-7A-1250LI	None	None	N/A	NCM	
4-EVK-7A-31250LI	None	None	N/A	NCM	
4CB0750S0Z0BACUGI	Contact IDT	None	N/A	NCM	
4CB0750S0Z0BACUGI8	Contact IDT	None	N/A	NCM	
4EA1000A0Z3AACUGI	None	None	N/A	NCM	
4EA1000A0Z3AACUGI8	None	None	N/A	NCM	
4EA1000A0Z3BACUGI	None	None	N/A	NCM	
4EA1000A0Z3BACUGI8	None	None	N/A	NCM	
4EA1000A0Z4AACUGI	None	None	N/A	NCM	
4EA1000A0Z4AACUGI8	None	None	N/A	NCM	
4EA1000A0Z4BACUGI	None	None	N/A	NCM	
4EA1000A0Z4BACUGI8	None	None	N/A	NCM	
4EA1000S0Z3AACUGI	None	None	N/A	NCM	
4EA1000S0Z3AACUGI8	None	None	N/A	NCM	
4EA1250A0Z3AACUGI	None	None	N/A	NCM	
4EA1250A0Z3AACUGI8	None	None	N/A	NCM	
4EA1250A0Z3BACUGI	None	None	N/A	NCM	
4EA1250A0Z3BACUGI8	None	None	N/A	NCM	
4EA1250A0Z4AACUGI	None	None	N/A	NCM	
4EA1250A0Z4AACUGI8	None	None	N/A	NCM	
4EA1250A0Z4BACUGI	None	None	N/A	NCM	
4EA1250A0Z4BACUGI8	None	None	N/A	NCM	
4EA1250S0Z3AACUGI	None	None	N/A	NCM	
4EA1250S0Z3AACUGI8	None	None	N/A	NCM	
4EA1250S1Z3AACUGI	None	None	N/A	NCM	
4EA1250S1Z3AACUGI8	None	None	N/A	NCM	
4EA1485A0Z4AACUGI	None	None	N/A	NCM	
4EA1485A0Z4AACUGI8	None	None	N/A	NCM	
4EA1562S0Z3AACUGI	None	None	N/A	NCM	
4EA1562S0Z3AACUGI8	None	None	N/A	NCM	
4HF050000Z3AACUGI	FXO-PC735R-50M	None	Now	NCM	
4HF050000Z3AACUGI8	FXO-PC735R-50M	None	Now	NCM	
4HF050000Z4AACUGI	FXO-LC735R-50M	None	Now	NCM	
4HF050000Z4AACUGI8	FXO-LC735R-50M	None	Now	NCM	
4HF074250Z3BBCUGI	FXO-PC726R-74.250M	None	Now	NCM	
4HF074250Z3BBCUGI8	FXO-PC726R-74.250M	None	Now	NCM	
4HF100000Z3ABCUGI	FXO-PC736R-100M	None	Now	NCM	
4HF100000Z3ABCUGI8	FXO-PC736R-100M	None	Now	NCM	
4HF100000Z3BACXGI	Contact IDT	None	N/A	NCM	
4HF100000Z3BACXGI8	Contact IDT	None	N/A	NCM	
4HF100000Z4AACTGI	FXO-LC535R-100M	None	Now	NCM	
4HF100000Z4AACTGI8	FXO-LC535R-100M	None	Now	NCM	
4HF100000Z4AACUGI	FXO-LC735R-100M	None	Now	NCM	
4HF100000Z4AACUGI8	FXO-LC735R-100M	None	Now	NCM	
4HF100000Z4ABCTGI	FXO-LC336-100M	None	Now	NCM	25ppm not available for -40+85C, only for 20+70C
4HF100000Z4ABCTGI8	FXO-LC336-100M	None	Now	NCM	25ppm not available for -40+85C, only for 20+70C
4HF100000Z4BACTGI	FXO-LC525R-100M	None	Now	NCM	
4HF100000Z4BACTGI8	FXO-LC525R-100M	None	Now	NCM	
4HF100000Z4BACUGI	FXO-LC725R-100M	None	Now	NCM	
4HF100000Z4BACUGI8	FXO-LC725R-100M	None	Now	NCM	
4HF106250Z3ABCTGI	FXO-PC536R-106.25M	None	Now	NCM	
4HF106250Z3ABCTGI8	FXO-PC536R-106.25M	None	Now	NCM	
4HF125000Z0AACUGI	None	None	N/A	NCM	
4HF125000Z0AACUGI8	None	None	N/A	NCM	
4HF125000Z3AACUGI	FXO-PC735R-125M	None	Now	NCM	
4HF125000Z3AACUGI8	FXO-PC735R-125M	None	Now	NCM	
4HF125000Z3ABCUGI	FXO-PC736R-125M	None	Now	NCM	
4HF125000Z3ABCUGI8	FXO-PC736R-125M	None	Now	NCM	



Integrated Device Technology, Inc.
6024, Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group	Remark
4HF125000Z3BACTGI	FX0-PC525R-125M	None	Now	NCM	
4HF125000Z3BACTGI8	FX0-PC525R-125M	None	Now	NCM	
4HF125000Z3BACXGI	Contact IDT	None	N/A	NCM	
4HF125000Z3BACXGI8	Contact IDT	None	N/A	NCM	
4HF125000Z4AACUGI	FXO-LC735R-125M	None	Now	NCM	
4HF125000Z4AACUGI8	FXO-LC735R-125M	None	Now	NCM	
4HF125000Z4ABCUGI	FXO-LC736R-125M	None	Now	NCM	
4HF125000Z4ABCUGI8	FXO-LC736R-125M	None	Now	NCM	
4HF125000Z4BACXGI	FXO-LC325R-125M	None	Now	NCM	
4HF125000Z4BACXGI8	FXO-LC325R-125M	None	Now	NCM	
4HF125000Z4BBCTGI	FXO-LC526R-125M	None	Now	NCM	
4HF125000Z4BBCTGI8	FXO-LC526R-125M	None	Now	NCM	
4HF125000Z4BBCUGI	FXO-LC726R-125M	None	Now	NCM	
4HF125000Z4BBCUGI8	FXO-LC726R-125M	None	Now	NCM	
4HF125000Z4BBCXGI	FXO-LC326-125M	None	Now	NCM	25ppm not available for -40+85C, only for 20+70C
4HF125000Z4BBCXGI8	FXO-LC326-125M	None	Now	NCM	25ppm not available for -40+85C, only for 20+70C
4HF133330Z3AACUGI	None	None	N/A	NCM	
4HF133330Z3AACUGI8	None	None	N/A	NCM	
4HF148500Z3ABCUGI	None	None	N/A	NCM	
4HF148500Z3ABCUGI8	None	None	N/A	NCM	
4HF155520Z3ABCUGI	None	None	N/A	NCM	
4HF155520Z3ABCUGI8	None	None	N/A	NCM	
4HF156250Z3AACTGI	FXO-PC535R-156.25M	None	Now	NCM	
4HF156250Z3AACTGI8	FXO-PC535R-156.25M	None	Now	NCM	
4HF156250Z3AACUGI	FXO-PC735R-156.25M	None	Now	NCM	
4HF156250Z3AACUGI8	FXO-PC735R-156.25M	None	Now	NCM	
4HF156250Z3AACXGI	Contact IDT	None	N/A	NCM	
4HF156250Z3AACXGI8	Contact IDT	None	N/A	NCM	
4HF156250Z3ABCTGI	FXO-PC536R-156.25M	None	Now	NCM	
4HF156250Z3ABCTGI8	FXO-PC536R-156.25M	None	Now	NCM	
4HF156250Z3ABCUGI	FXO-PC736R-156.25M	None	Now	NCM	
4HF156250Z3ABCUGI8	FXO-PC736R-156.25M	None	Now	NCM	
4HF156250Z3BACTGI	FXO-PC525R-156.25M	None	Now	NCM	
4HF156250Z3BACTGI8	FXO-PC525R-156.25M	None	Now	NCM	
4HF156250Z3BACUGI	FXO-PC725R-156.25M	None	Now	NCM	
4HF156250Z3BACUGI8	FXO-PC725R-156.25M	None	Now	NCM	
4HF156250Z3BACXGI	Contact IDT	None	N/A	NCM	
4HF156250Z3BACXGI8	Contact IDT	None	N/A	NCM	
4HF156250Z3BBCTGI	FXO-PC526R-156.25M	None	Now	NCM	
4HF156250Z3BBCTGI8	FXO-PC526R-156.25M	None	Now	NCM	
4HF156250Z4AACUGI	FXO-LC735R-156.25M	None	Now	NCM	
4HF156250Z4AACUGI8	FXO-LC735R-156.25M	None	Now	NCM	
4HF156250Z4AACXGI	FXO-LC335R-156.25M	None	Now	NCM	
4HF156250Z4AACXGI8	FXO-LC335R-156.25M	None	Now	NCM	
4HF156250Z4BACTGI	FXO-LC525R-156.25M	None	Now	NCM	
4HF156250Z4BACTGI8	FXO-LC525R-156.25M	None	Now	NCM	
4HF156250Z4BBCXGI	FXO-LC326-156.25M	None	Now	NCM	25ppm not available for -40+85C, only for 20+70C
4HF156250Z4BBCXGI8	FXO-LC326-156.25M	None	Now	NCM	25ppm not available for -40+85C, only for 20+70C
4HF156253Z3ABCTGI	FXO-PC536R-156.25M	None	Now	NCM	
4HF156253Z3ABCTGI8	FXO-PC536R-156.25M	None	Now	NCM	
4HF156253Z3ABCUGI	FXO-PC736R-156.25M	None	Now	NCM	
4HF156253Z3ABCUGI8	FXO-PC736R-156.25M	None	Now	NCM	
4HF187510Z3AACUGI	FXO-PC735R-187.51M	None	Now	NCM	
4HF187510Z3AACUGI8	FXO-PC735R-187.51M	None	Now	NCM	
4HF212500Z4AACXGI	FXO-LC335R-212.5M	None	Now	NCM	



Integrated Device Technology, Inc.
6024, Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group	Remark
4HF21250024AACXG18	FXO-LC335R-212.5M	None	Now	NCM	
4HF50000024AACUG1	FXO-LC735R-500M	None	Now	NCM	
4HF50000024AACUG18	FXO-LC735R-500M	None	Now	NCM	
4HF61440024AACTGI	FXO-LC535R-614.4M	None	Now	NCM	
4HF61440024AACTGI8	FXO-LC535R-614.4M	None	Now	NCM	
4HF622080Z3ABCUG1	FXO-PC736R-622.08M	None	Now	NCM	
4HF622080Z3ABCUG18	FXO-PC736R-622.08M	None	Now	NCM	
4MA025000Z3AACUG1	FXO-PC735R-25M	None	Now	NCM	
4MA025000Z3AACUG18	FXO-PC735R-25M	None	Now	NCM	
4MA025000Z4AACTGI	FXO-LC535R-25M	None	Now	NCM	
4MA025000Z4AACTGI8	FXO-LC535R-25M	None	Now	NCM	
4MA050000Z4AACUG1	FXO-LC735R-50M	None	Now	NCM	
4MA050000Z4AACUG18	FXO-LC735R-50M	None	Now	NCM	
4MA074175Z4AACUG1	FXO-LC735R-74.175M	None	Now	NCM	
4MA074175Z4AACUG18	FXO-LC735R-74.175M	None	Now	NCM	
4MA074250Z4AACUG1	FXO-LC735R-74.250M	None	Now	NCM	
4MA074250Z4AACUG18	FXO-LC735R-74.250M	None	Now	NCM	
4MA075000Z4AACTGI	FXO-LC535R-75M	None	Now	NCM	
4MA075000Z4AACTGI8	FXO-LC535R-75M	None	Now	NCM	
4MA078300Z4BACUG1	FXO-LC725R-78.3M	None	Now	NCM	
4MA078300Z4BACUG18	FXO-LC725R-78.3M	None	Now	NCM	
4MA085000Z3AACUG1	FXO-PC735R-85M	None	Now	NCM	
4MA085000Z3AACUG18	FXO-PC735R-85M	None	Now	NCM	
4MA099000Z4BACUG1	FXO-LC725R-99M	None	Now	NCM	
4MA099000Z4BACUG18	FXO-LC725R-99M	None	Now	NCM	
4MA100000Y3ABCUG	FXO-PC736-100M	None	Now	NCM	
4MA100000Y3ABCUG8	FXO-PC736-100M	None	Now	NCM	
4MA100000Z3AACTGI	FXO-PC535R-100M	None	Now	NCM	
4MA100000Z3AACTGI8	FXO-PC535R-100M	None	Now	NCM	
4MA100000Z3AACUG1	FXO-PC735R-100M	None	Now	NCM	
4MA100000Z3AACUG18	FXO-PC735R-100M	None	Now	NCM	
4MA100000Z4AACTGI	FXO-LC535R-100M	None	Now	NCM	
4MA100000Z4AACTGI8	FXO-LC535R-100M	None	Now	NCM	
4MA100000Z4AACUG1	FXO-LC735R-100M	None	Now	NCM	
4MA100000Z4AACUG18	FXO-LC735R-100M	None	Now	NCM	
4MA100000Z4BACTGI	FXO-LC525R-100M	None	Now	NCM	
4MA100000Z4BACTGI8	FXO-LC525R-100M	None	Now	NCM	
4MA100000Z4BACUG1	FXO-LC725R-100M	None	Now	NCM	
4MA100000Z4BACUG18	FXO-LC725R-100M	None	Now	NCM	
4MA106250Z3AACUG1	FXO-PC735R-106.25M	None	Now	NCM	
4MA106250Z3AACUG18	FXO-PC735R-106.25M	None	Now	NCM	
4MA120000Z4BACUG1	FXO-LC725R-120M	None	Now	NCM	
4MA120000Z4BACUG18	FXO-LC725R-120M	None	Now	NCM	
4MA125000Y4AACUG1	FXO-LC735R-125M	None	Now	NCM	
4MA125000Y4AACUG18	FXO-LC735R-125M	None	Now	NCM	
4MA125000Z3AACTGI	FXO-PC535R-125M	None	Now	NCM	
4MA125000Z3AACTGI8	FXO-PC535R-125M	None	Now	NCM	
4MA125000Z3AACUG1	FXO-PC735R-125M	None	Now	NCM	
4MA125000Z3AACUG18	FXO-PC735R-125M	None	Now	NCM	
4MA125000Z3BACUG1	FXO-PC725R-125M	None	Now	NCM	
4MA125000Z3BACUG18	FXO-PC725R-125M	None	Now	NCM	
4MA125000Z4AACTGI	FXO-LC535R-125M	None	Now	NCM	
4MA125000Z4AACTGI8	FXO-LC535R-125M	None	Now	NCM	
4MA125000Z4AACUG1	FXO-LC735R-125M	None	Now	NCM	
4MA125000Z4AACUG18	FXO-LC735R-125M	None	Now	NCM	
4MA125000Z4BACUG1	FXO-LC725R-125M	None	Now	NCM	
4MA125000Z4BACUG18	FXO-LC725R-125M	None	Now	NCM	
4MA125006Y3AACUG1	FXO-PC735R-125.006	None	Now	NCM	
4MA125006Y3AACUG18	FXO-PC735R-125.006	None	Now	NCM	
4MA125061Y3AACUG1	FXO-PC735R-125.061M	None	Now	NCM	
4MA125061Y3AACUG18	FXO-PC735R-125.061M	None	Now	NCM	
4MA13330Z3AACTGI	FXO-PC535R-133.33M	None	Now	NCM	
4MA13330Z3AACTGI8	FXO-PC535R-133.33M	None	Now	NCM	
4MA13330Z3AACUG1	FXO-PC735R-133.33M	None	Now	NCM	
4MA13330Z3AACUG18	FXO-PC735R-133.33M	None	Now	NCM	
4MA13330Z4AACTGI	FXO-LC535R-133.33M	None	Now	NCM	
4MA13330Z4AACTGI8	FXO-LC535R-133.33M	None	Now	NCM	



Integrated Device Technology, Inc.
6024, Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group	Remark
4MA13333Z3AACUGI	FXO-PC735R-133.333M	None	Now	NCM	
4MA13333Z3AACUGI8	FXO-PC735R-133.333M	None	Now	NCM	
4MA148500Z3AACUGI	FXO-PC735R-148.5M	None	Now	NCM	
4MA148500Z3AACUGI8	FXO-PC735R-148.5M	None	Now	NCM	
4MA148500Z4AACTGI	FXO-LC535R-148.5M	None	Now	NCM	
4MA148500Z4AACTGI8	FXO-LC535R-148.5M	None	Now	NCM	
4MA148500Z4AACUGI	FXO-LC735R-148.5M	None	Now	NCM	
4MA148500Z4AACUGI8	FXO-LC735R-148.5M	None	Now	NCM	
4MA148500Z4BACTGI	FXO-LC525R-148.5M	None	Now	NCM	
4MA148500Z4BACTGI8	FXO-LC525R-148.5M	None	Now	NCM	
4MA148500Z4BACUGI	FXO-LC725R-148.5M	None	Now	NCM	
4MA148500Z4BACUGI8	FXO-LC725R-148.5M	None	Now	NCM	
4MA150000Z3AACTGI	FXO-PC535R-150M	None	Now	NCM	
4MA150000Z3AACTGI8	FXO-PC535R-150M	None	Now	NCM	
4MA150000Z3AACUGI	FXO-PC735R-150M	None	Now	NCM	
4MA150000Z3AACUGI8	FXO-PC735R-150M	None	Now	NCM	
4MA150000Z4AACTGI	FXO-LC535R-150M	None	Now	NCM	
4MA150000Z4AACTGI8	FXO-LC535R-150M	None	Now	NCM	
4MA150000Z4AACUGI	FXO-LC735R-150M	None	Now	NCM	
4MA150000Z4AACUGI8	FXO-LC735R-150M	None	Now	NCM	
4MA150000Z4BACTGI	FXO-LC525R-150M	None	Now	NCM	
4MA150000Z4BACTGI8	FXO-LC525R-150M	None	Now	NCM	
4MA155520Z3AACTGI	FXO-PC535R-155.52M	None	Now	NCM	
4MA155520Z3AACTGI8	FXO-PC535R-155.52M	None	Now	NCM	
4MA155520Z3AACUGI	FXO-PC735R-155.52M	None	Now	NCM	
4MA155520Z3AACUGI8	FXO-PC735R-155.52M	None	Now	NCM	
4MA155520Z3BACUGI	FXO-PC725R-155.52M	None	Now	NCM	
4MA155520Z3BACUGI8	FXO-PC725R-155.52M	None	Now	NCM	
4MA155520Z4AACTGI	FXO-LC535R-155.52M	None	Now	NCM	
4MA155520Z4AACTGI8	FXO-LC535R-155.52M	None	Now	NCM	
4MA155520Z4AACUGI	FXO-LC735R-155.52M	None	Now	NCM	
4MA155520Z4AACUGI8	FXO-LC735R-155.52M	None	Now	NCM	
4MA156250Z3AACTGI	FXO-PC535R-156.25M	None	Now	NCM	
4MA156250Z3AACTGI8	FXO-PC535R-156.25M	None	Now	NCM	
4MA156250Z3AACUGI	FXO-PC735R-156.25M	None	Now	NCM	
4MA156250Z3AACUGI8	FXO-PC735R-156.25M	None	Now	NCM	
4MA156250Z3BACTGI	FXO-PC525R-156.25M	None	Now	NCM	
4MA156250Z3BACTGI8	FXO-PC525R-156.25M	None	Now	NCM	
4MA156250Z3BACUGI	FXO-PC725R-156.25M	None	Now	NCM	
4MA156250Z3BACUGI8	FXO-PC725R-156.25M	None	Now	NCM	
4MA156250Z4AACTGI	FXO-LC535R-156.25M	None	Now	NCM	
4MA156250Z4AACTGI8	FXO-LC535R-156.25M	None	Now	NCM	
4MA156250Z4AACUGI	FXO-LC735R-156.25M	None	Now	NCM	
4MA156250Z4AACUGI8	FXO-LC735R-156.25M	None	Now	NCM	
4MA156250Z4BACTGI	FXO-LC525R-156.25M	None	Now	NCM	
4MA156250Z4BACTGI8	FXO-LC525R-156.25M	None	Now	NCM	
4MA156250Z4BACUGI	FXO-LC725R-156.25M	None	Now	NCM	
4MA156250Z4BACUGI8	FXO-LC725R-156.25M	None	Now	NCM	
4MA156600Z4BACUGI	FXO-LC725R-156.25M	None	Now	NCM	
4MA156600Z4BACUGI8	FXO-LC725R-156.25M	None	Now	NCM	
4MA159375Z4AACTGI	FXO-LC535R-159.375M	None	Now	NCM	
4MA159375Z4AACTGI8	FXO-LC535R-159.375M	None	Now	NCM	
4MA187500Z4BACTGI	FXO-LC525R-187.5M	None	Now	NCM	
4MA187500Z4BACTGI8	FXO-LC525R-187.5M	None	Now	NCM	
4MA187510Z3AACUGI	FXO-PC735R-187.510M	None	Now	NCM	
4MA187510Z3AACUGI8	FXO-PC735R-187.510M	None	Now	NCM	
4MA200000Z3AACUGI	FXO-PC735R-200M	None	Now	NCM	
4MA200000Z3AACUGI8	FXO-PC735R-200M	None	Now	NCM	
4MA200000Z3BACUGI	FXO-PC725R-200M	None	Now	NCM	
4MA200000Z3BACUGI8	FXO-PC725R-200M	None	Now	NCM	
4MA200000Z4AACTGI	FXO-LC535R-200M	None	Now	NCM	
4MA200000Z4AACTGI8	FXO-LC535R-200M	None	Now	NCM	
4MA200000Z4AACUGI	FXO-LC735R-200M	None	Now	NCM	
4MA200000Z4AACUGI8	FXO-LC735R-200M	None	Now	NCM	
4MA200000Z4BACTGI	FXO-LC525R-200M	None	Now	NCM	
4MA200000Z4BACTGI8	FXO-LC525R-200M	None	Now	NCM	
4MA200000Z4BACUGI	FXO-LC725R-200M	None	Now	NCM	



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group	Remark
4MA200000Z4BACUGI8	FXO-LC725R-200M	None	Now	NCM	
4MA212500Z3AACUGI	FXO-PC735R-212.5M	None	Now	NCM	
4MA212500Z3AACUGI8	FXO-PC735R-212.5M	None	Now	NCM	
4MA212500Z4AACTGI	FXO-LC535R-212.5M	None	Now	NCM	
4MA212500Z4AACTGI8	FXO-LC535R-212.5M	None	Now	NCM	
4MA212500Z4AACUGI	FXO-LC735R-212.5M	None	Now	NCM	
4MA212500Z4AACUGI8	FXO-LC735R-212.5M	None	Now	NCM	
4MA23333Z4AACUGI	FXO-LC735R-233.333M	None	Now	NCM	
4MA23333Z4AACUGI8	FXO-LC735R-233.333M	None	Now	NCM	
4MA23333Z4BACUGI	FXO-LC725R-233.333M	None	Now	NCM	
4MA23333Z4BACUGI8	FXO-LC725R-233.333M	None	Now	NCM	
4MA250000Z4AACTGI	FXO-LC535R-250M	None	Now	NCM	
4MA250000Z4AACTGI8	FXO-LC535R-250M	None	Now	NCM	
4MA300000Z4AACUGI	FXO-LC735R-300M	None	Now	NCM	
4MA300000Z4AACUGI8	FXO-LC735R-300M	None	Now	NCM	
4MA312500Z3AACUGI	FXO-PC735R-312.515M	None	Now	NCM	
4MA312500Z3AACUGI8	FXO-PC735R-312.515M	None	Now	NCM	
4MA312515Y3AACUGI	FXO-PC735R-312.515M	None	Now	NCM	
4MA312515Y3AACUGI8	FXO-PC735R-312.515M	None	Now	NCM	
4MA312653Y3AACUGI	FXO-PC735R-312.653M	None	Now	NCM	
4MA312653Y3AACUGI8	FXO-PC735R-312.653M	None	Now	NCM	
4MA400000Y3AACTGI	FXO-PC535R-400M	None	Now	NCM	
4MA400000Y3AACTGI8	FXO-PC535R-400M	None	Now	NCM	
4ZA078115Y3AACUGI	FXO-PC735R-78.115M	None	Now	NCM	
4ZA078115Y3AACUGI8	FXO-PC735R-78.115M	None	Now	NCM	
4ZA078125Z3AZCUGI	FXO-PC730R78.125M	None	Now	NCM	
4ZA078125Z3AZCUGI8	FXO-PC730R78.125M	None	Now	NCM	
4ZA125000Y4BACTGI	FXO-LC525R-125M	None	Now	NCM	
4ZA125000Y4BACTGI8	FXO-LC525R-125M	None	Now	NCM	
4ZA148500Y4AACTGI	FXO-LC535R-148.5M	None	Now	NCM	
4ZA148500Y4AACTGI8	FXO-LC535R-148.5M	None	Now	NCM	
4ZA148500Y4BACTGI	FXO-LC525R-148.5M	None	Now	NCM	
4ZA148500Y4BACTGI8	FXO-LC525R-148.5M	None	Now	NCM	
4ZA156240Y3BACXGI	Contact IDT	None	N/A	NCM	
4ZA156240Y3BACXGI8	Contact IDT	None	N/A	NCM	
4ZA156250Y3BACXGI	Contact IDT	None	N/A	NCM	
4ZA156250Y3BACXGI8	Contact IDT	None	N/A	NCM	
4ZB155520Y4ABCUGI	None	None	N/A	NCM	
4ZB155520Y4ABCUGI8	None	None	N/A	NCM	
4ZB156250Y4ABCUGI	None	None	N/A	NCM	
4ZB156250Y4ABCUGI8	None	None	N/A	NCM	
4ZH125000Y4BBCUG	FXO-LC726-125M	None	Now	NCM	
4ZH125000Y4BBCUG8	FXO-LC726-125M	None	Now	NCM	
4ZL035328Y0AACUGI	None	None	N/A	NCM	
4ZL035328Y0AACUGI8	None	None	N/A	NCM	
4ZL070656Y0AACUGI	None	None	N/A	NCM	
4ZL070656Y0AACUGI8	None	None	N/A	NCM	
4ZY125000Z3AACTGI	FXO-PC535R-125M	None	Now	NCM	
4ZY125000Z3AACTGI8	FXO-PC535R-125M	None	Now	NCM	