

Infonote

AO-IN-2022-042-I

OSLON[®] UV 3636 – Plating
material change from NiPdAu to
NiAu

01.11.2022

Dear Customer,

please take note of this **Infonote**.

This customer notification is for information only and does not require customer approval.


Objective: OSLON® UV 3636 - Plating material change from NiPdAu to NiAu

Affected products: SU CULBN1.VC
SU CULDN1.VC

Reason for change: Discontinuation from supplier


Current status

Plating material: NiPdAu
Current visual appearance:



New status

Plating material: NiAu
Slightly changed visual appearance:



Description of change:

Time schedule: Starting from 01.11.2022

Assessment: **No change in fit, form function and reliability, aside from the slight change in appearance.**

Material (Q-no.) Q Description

Q65113A2463 SU CULBN1.VC-AGAM-67-4F4G-30-R18
Q65113A2532 SU CULBN1.VC-AGAM-67-4F4G-30-R18B
Q65113A2366 SU CULBN1.VC-AGAY-67-4F4G-30-R18
Q65113A2462 SU CULDN1.VC-MAMF-67-4E4F-350-R18
Q65113A2533 SU CULDN1.VC-MAMF-67-4E4F-350-R18B
Q65113A2365 SU CULDN1.VC-MAMP-67-4E4F-350-R18