


Sensor

Issue Date
Mar. 6, 2019
No. AXA-DT180037

Discontinuation Notice of SENSOR

Product Discontinuation	Recommended Replacement
Name of products	Name of products
	No recommended Replacement
Model TL-PP702 Model W2DH-01 Model W2DL-02	

[Product Discontinuation and recommended replacement]

Product discontinuation	Recommended replacement	Final order entry date
TL-PP702	No recommended replacement	The end of June, 2019
W2DH-01	No recommended replacement	The end of June, 2019
W2DL-02	No recommended replacement	The end of June, 2019

Specifications and prices in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.