



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000995

DATE: 21-May-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS28E01P-W0V+1T	N/A	21-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX17482GTL+T	N/A	21-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	MAX751CPA+	N/A	21-May-2021	12-Nov-2021	Part can no longer be manufactured
Discontinuance	VT1536MBFQX	N/A	15-Jul-2020	12-Nov-2021	Part can no longer be manufactured
Discontinuance	VT231TFCX-ADJ	N/A	15-Jun-2020	12-Nov-2021	Part can no longer be manufactured
Discontinuance	VT232TFCX-ADJ	MAX20710EPL+T	15-Jun-2020	12-Nov-2021	Part can no longer be manufactured
Discontinuance	VT233TFC-ADJ	N/A	15-Jun-2020	12-Nov-2021	Part can no longer be manufactured
Discontinuance	VT233TFCX-ADJ	N/A	15-Jun-2020	12-Nov-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 21-Jun-2020