

PRODUCT DISCONTINUATION



PD_085_14

■ Last order:	2014-12-31
■ Last delivery:	2015-06-30

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
BF 1005 E6327	SP000010946	BF1005E6327HTSA1	SOT143			None	
BF 1005S E6327	SP000010949	BF1005SE6327HTSA1	SOT143			None	
BF 1009S E6327	SP000010955	BF1009SE6327HTSA1	SOT143			None	
BF 1009SR E6327	SP000010956	BF1009SRE6327HTSA1	SOT143			None	
BF 2030 E6814	SP000012219	BF2030E6814HTSA1	SOT143			None	
BF 2030W H6814	SP000752012	BF2030WH6814XTSA1	SOT343			None	
BF 5020W H6327	SP000753486	BF5020WH6327XTSA1	SOT343			None	
BG 3123 H6327	SP000753490	BG3123H6327XTSA1	SOT363			None	
BG 3123R H6327	SP000753492	BG3123RH6327XTSA1	SOT363			None	
BG 3430R H6327	SP000753498	BG3430RH6327XTSA1	SOT363			None	
BG 5120K H6327	SP000753500	BG5120KH6327XTSA1	SOT363			None	
BG 5412K H6327	SP000753502	BG5412KH6327XTSA1	SOT363			None	

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!