


Product Or Individual Q-Code Discontinuation (acc. JEDEC J-STD-048)  
**OS-PDN-2021-018**

04 May 2021

---

Last order: 01 November 2021  
Last delivery: 01 October 2022

---



Please direct your feedback to your local Sales office.

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
<b>LE UW U1A4 11</b>	<b>all</b>					
LE UW U1A4 11-6R7R-fcbB68-T05	Q65112A0784	OSRAM OSTAR	No sufficient future volume forecast	KW HKL531.TE-F0F8-ebvFcbB46-4LZL-A00-S	Q65112A8333	OSLON
LE UW U1A4 11-N38N46-fcbB68-T05-HAN	Q65112A5040	OSRAM OSTAR	No sufficient future volume forecast	KW HKL531.TE-F0F8-ebvFcbB46-4LZL-A00-S	Q65112A8333	OSLON
LE UW U1A4 11-N42N46-fcbB68-T05-HAN	Q65112A5456	OSRAM OSTAR	No sufficient future volume forecast	KW HKL531.TE-F0F8-ebvFcbB46-4LZL-A00-S	Q65112A8333	OSLON
<b>LE UW U1A5 11</b>	<b>all</b>					
LE UW U1A5 11-A1A4-fcbB68-T05	Q65112A3461	OSRAM OSTAR	No sufficient future volume forecast	KW HLL531.TE-G0G8-ebvFcbB46-RS5R-A00-S	Q65112A8357	OSLON
LE UW U1A5 11-A2A3-fcbB68-T05-HAN	Q65112A3695	OSRAM OSTAR	No sufficient future volume forecast	KW HLL531.TE-G0G8-ebvFcbB46-RS5R-A00-S	Q65112A8357	OSLON
LE UW U1A5 11-A1A2-fcbB68-T05-HAN	Q65112A3696	OSRAM OSTAR	No sufficient future volume forecast	KW HLL531.TE-G0G8-ebvFcbB46-RS5R-A00-S	Q65112A8357	OSLON
LE UW U1A5 11-A3A4-fcbB68-T05-HAN	Q65112A4790	OSRAM OSTAR	No sufficient future volume forecast	KW HLL531.TE-G0G8-ebvFcbB46-RS5R-A00-S	Q65112A8357	OSLON
LE UW U1A5 11-A1A4-ebxD68-T05-XX	Q65112A8520	OSRAM OSTAR	No sufficient future volume forecast	KW HLL531.TE-G0G8-ebvFcbB46-RS5R-A00-S	Q65112A8357	OSLON