

Date: 05-04-21 |

Attention: CDE Sales and Distribution Partners

Discontinuation Notice for Specific Snap-in Capacitor Part Numbers

Parts Affected...

- Entire series
- Part# XXXXX
- Select part#s...see attached list

Reason for discontinuation...

- Declining market demand
- Change in strategic market focus
- Material no longer available for manufacturing

-

Effective date: 05-04-21

Last time buy...

- CDE will accept orders through 06-04-21 on items in CDE stock. If there is no factory stock, an MOQ of 3,000 pieces applies.
- Not applicable

Possible replacement series...

- See attached list for suggested alternatives
- No replacement at this time

CDE Discontinued Parts CDE Suggested Alternative

380LQ152M080H022	380LQ152M080H012
380LX822M035J032	380LX822M035J022
381LQ151M450H042	381LQ151M450H032
381LR101M400H022	381LR101M400H012
381LX101M450J022	381LX101M450H022
381LX102M080J012	381LX102M080H012
381LX103M035J052	381LX103M035J452
381LX121M400J022	381LX121M400J012
381LX122M100H032	381LX122M100H022
381LX182M080H032	381LX182M080H022
381LX182M080H042	381LX182M080H022
381LX182M080J032	381LX182M080H022
381LX272M050J012	381LX272M050H012
381LX820M400H012	381LR820M400H012
SLP101M450A5P3	SLP101M450A3P3
SLP101M450C3P3	SLP101M450A3P3
SLP103M063H4P3	SLP103M063H9P3
SLP122M200H5P3	SLP122M200H3P3
SLP181M250C1P3	SLP181M250A1P3
SLP182M200H4P3	SLP182M200H7P3
SLP331M200C3P3	SLP331M200C1P3
SLP331M450H7P3	SLP331M450H5P3
SLP332M080C4P3	SLP332M080C7P3
SLP471M450H9P3	SLP471M450H4P3
SLP472M063H3P3	SLP472M063H1P3
SLP681M200C7P3	SLP681M200C5P3
SLPX101M385A3P3	SLPX101M400A3P3
SLPX102M250E9P3	SLPX102M250E4P3
SLPX102M250H5P3	SLPX102M250H3P3
SLPX123M050H7P3	SLPX123M050H5P3
SLPX152M200H4P3	SLPX152M200H7P3
SLPX331M200A3P3	SLPX331M200A1P3
SLPX471M200C3P3	SLPX471M200A3P3
SLPX471M450H9P3	SLPX471M450H4P3