

PRODUCT DISCONTINUATION NOTICE

SUBJECT: Radial leaded Film Capacitor ECQ-U2A(G) / ECQ-E2W(C)

BULLETIN #: DCN.PG42.03.07.09

Date: March 6, 2009

Page 1 of 1

LAST TIME BUY: April 30, 2009

LAST TIME SHIPMENT: June 30, 2009

SUGGESTED REPLACEMENT: Please see below

DETAILS:

The series affected

ECQ-U2A(G) Metallized Polyester Film Capacitor

ECQ-E2W(C) Noise Suppression Film Capacitor

The recommended replacements are categorized by voltage

* Please note that these are not direct replacements.

 $ECQ-U2A(G) \rightarrow ECQ-U(L) / ECQ-U3A(G)$

 $ECQ-E2W(C) \rightarrow ECQ-E2W(H)$