

**Part Change for Marktech Optoelectronics Photo Detectors**

Announced April 07, 2017

Effective Immediately

The following parts are affected by this announcement:

**MTPC5.0PV1-5 (old number) changed to MT03-001 (new number)**

**MTPC10.0PV1-5 (old number) changed to MT03-002 (new number)**

**MTPS15.0PV1-5 (old number) changed to MT03-003 (new number)**

**MTQD5.8PV1-5 (old number) changed to MT03-004 (new number)**

**DESCRIPTION OF CHANGE**

Effective immediately - Marktech Optoelectronics has changed the part number of several photodetector products in order to better coincide with their existing software system.

**IMPACT OF CHANGE**

Marktech Optoelectronics believes this change will be transparent to the majority of customers / end users, There is no direct impact on the product performance as the change only affects the component part number. It is the recommendation of Marktech engineering that all customers be informed of this change.