



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000872

DATE: 07-Aug-2018

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX15000AEUB+	N/A			Part reactivated from prior notice: M000870
Reactivation	MAX15000AEUB+T	N/A			Part reactivated from prior notice: M000870
Reactivation	MAX20094ATIA/VY+	N/A			Part reactivated from prior notice: M000866
Reactivation	MAX20098ATEA/VY+	N/A			Part reactivated from prior notice: M000867
Lead-Free Conversion	DS2433X-300-EC#TW	N/A	07-Aug-2019	06-Feb-2020	Part is leaded. Request information on lead-free version
Discontinuance	73M1903-IM/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	73M1903-IMR/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	73M1906B-IMR/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	73M1906B-IVT/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	73M1906B-IVTR/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	73M1916-IVT/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	73M1916-IVTR/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	73S1215F-68IM/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8009R-IM/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8009R-IMR/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	78P2342JAT-IGT/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	78P2344JAT-IGT/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	78P2344JAT-IGTR/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	78Q2120C09-64CGT/F	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	DS1809Z-050+	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	MAX14576EVB+	MAX14576CVB+	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	MAX14576EVB+T	MAX14576CVB+T	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	MAX14636EVB+	MAX14636CVB+	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	MAX14637EVB+	MAX14637CVB+	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	MAX14637EVB+T	MAX14637CVB+T	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	MAX16933ATIR/VY+	MAX16933CATIR/VY+	07-Aug-2018	07-Aug-2018	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 07-Sep-2018

Discontinuance	MAX21000+TWCHS	N/A	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	MAX2141ETH+	N/A	07-Aug-2018	07-Aug-2018	Part can no longer be manufactured
Discontinuance	MAX30033CTA+	MAX30034CTA+	07-Aug-2019	06-Feb-2020	The part was not released
Discontinuance	MAX66240ETB-A+	MAX66240ETB+	07-Aug-2018	07-Aug-2018	Part can no longer be manufactured
Discontinuance	MAX66240ETB-A+T	MAX66240ETB+T	07-Aug-2018	07-Aug-2018	Part can no longer be manufactured
Discontinuance	MAX66240ISA+	MAX66240ESA+	07-Aug-2018	07-Aug-2018	Part can no longer be manufactured
Discontinuance	MAX66242ETB-A+	MAX66242ETB+	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	MAX66242ETB-A+T	MAX66242ETB+T	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	MAX66242ISA-A+	MAX66242ESA+	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	MAX66242ISA-A+T	MAX66242ESA+T	07-Aug-2019	06-Feb-2020	Part can no longer be manufactured
Discontinuance	MAX9217ECM+CPG	MAX9217ECM+	07-Aug-2019	06-Feb-2020	The part was not released
Discontinuance	MAX9288GTM+	MAX9288GGM/VY+	07-Aug-2018	07-Aug-2018	The part was not released
Discontinuance	MAX9860ETG+	N/A	07-Aug-2019	06-Feb-2020	Reactivation