



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000761

DATE: 30-May-13

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	DS26521DK	N/A	N/A	N/A	Reactivation
Discontinuance	MAX17830EVKIT#	MAX17830EVMINIQU#	30-Nov-2013	30-May-2015	Part was never released
Discontinuance	MAX1270EVKIT	MAX1270EVKIT+	30-Nov-2013	30-May-2015	Part number has changed
Discontinuance	MAX14921EVKIT	MAX14921EVKIT#	30-Nov-2013	30-May-2015	Part number has changed
Discontinuance	MAX1300EVKIT+	MAX1300AEVKIT#	30-Nov-2013	30-May-2015	Part has direct replacement
Discontinuance	DS1267-050+	DS1267BE-050+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1267-100+	DS1267BE-100+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1267E-100+	DS1267BE-100+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1267E-100+T&R	DS1267BE-100+T/R	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1267E-50+	DS1267BE-050+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1267E-50+T&R	DS1267BE-050+T/R	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1267S-050+	DS1267BS-050+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1267S-050+T&R	DS1267BS-050+T/R	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1267S-100	DS1267BS-100+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1267S-100+	DS1267BS-100+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1267S-100+T&R	DS1267BS-100+T/R	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1743-100	N/A	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1868-100+	DS1868BE-100+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1868-50+	DS1868BE-050+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1868E-100+	DS1868BE-100+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1868E-100+T&R	DS1868BE-100+T/R	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1868E-50+	DS1868BE-050+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1868E-50+T&R	DS1868BE-050+T/R	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1868S-100+	DS1868BS-100+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1868S-100+T&R	DS1868BS-100+T/R	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS1868S-50+	DS1868BS-50+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	DS2506+	DS2506S+, DS2505+	30-May-2013	30-May-2015	No longer manufacturable
Discontinuance	ZLR323H2832GR0541T	MAXQ61H-2501+	30-Nov-2013	30-May-2015	No longer manufacturable
Discontinuance	ZLR323S2832GR0641T	MAXQ61H-2501+	30-Nov-2013	30-May-2015	No longer manufacturable