

PCN Number:	20140428000	PCN Date:	05/12/2014
Title:	Datasheet update for LP8545, LP8550, LP8551, LP8552, and LP8553		
Customer Contact:	PCN Manager	Phone:	+1(214) 480-6037
		Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
		<input type="checkbox"/>	Wafer Bump Site
		<input type="checkbox"/>	Wafer Bump Material
		<input type="checkbox"/>	Wafer Bump Process
		<input type="checkbox"/>	Wafer Fab Site
		<input type="checkbox"/>	Wafer Fab Materials
		<input type="checkbox"/>	Wafer Fab Process

PCN Details

Description of Change:

The product datasheet(s) is being update, to add note to EEPROM configuration.

The following change history provides further details. These changes may be reviewed at the datasheet links provided

LP8545



SNVS635D – APRIL 2010 – REVISED DECEMBER 2013

www.ti.com

REVISION HISTORY

Changes from Revision C (March 2013) to Revision D	Page
• Added note re: EEPROM configuration	19
• Added note re: EEPROM configuration	32



LP8550

www.ti.com

SNVS657D – SEPTEMBER 2010 – REVISED JANUARY 2014

REVISION HISTORY

Changes from Revision C (May 2013) to Revision D	Page
• replace product brief with full data sheet	1
• Added note re EEPROM	19
• Added note re: EEPROM	31

REVISION HISTORY

Changes from Revision C (April 2013) to Revision D	Page
• Changed top mark drawing to reflect TI nomenclature	2
• Added EEPROM note	17
• Added EEPROM note	30

REVISION HISTORY

Changes from Revision C (March 2013) to Revision D	Page
• Added add note re: EEPROM configuration	20
• Added add note re: EEPROM configuration	33

REVISION HISTORY

Changes from Original (May 2013) to Revision B	Page
• Added note re: EEPROM configuration	18
• Added note re: EEPROM configuration	30

The datasheet number will be changing.

Device Family	Change From:	Change To:
LP8545	SNVS635C	SNVS635D
LP8550	SNVS657C	SNVS657D
LP8551	SNVS673C	SNVS673D
LP8552	SNVS693	SNVS693D
LP8553	SNVS701A	SNVS701B

The updated datasheet(s) can be accessed by the following link(s):

- <http://www.ti.com/product/lp8545>
- <http://www.ti.com/product/lp8550>
- <http://www.ti.com/product/lp8551>
- <http://www.ti.com/product/lp8552>
- <http://www.ti.com/product/lp8553>

Reason for Change:			
Customer/marketing need			
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):			
Changes to product identification resulting from this PCN:			
None.			
Product Affected:			
LP8545SQ/NOPB	LP8551TLX/NOPB	LP8552TLE/NOPB	LP8552TLX-E05/NOPB
LP8545SSE/NOPB	LP8552TLE-E00/NOPB	LP8552TLX-E00/NOPB	LP8552TLX-E06/NOPB
LP8545SQX/NOPB	LP8552TLE-E01/NOPB	LP8552TLX-E00/S1	LP8552TLX/NOPB
LP8550TLE/NOPB	LP8552TLE-E04/NOPB	LP8552TLX-E00/S7002840	LP8552TLX/S7002721
LP8550TLX/NOPB	LP8552TLE-E05/NOPB	LP8552TLX-E01/NOPB	LP8553TLE/NOPB
LP8551TLE/NOPB	LP8552TLE-E06/NOPB	LP8552TLX-E04/NOPB	LP8553TLX/NOPB

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com