

**Corporate Headquarters**

5570 Enterprise Parkway  
 Fort Myers, FL 33905  
<http://www.FOXONLINE.com>

**Sales**

1-888-GET-2-FOX (1-888-438-2369) or  
 1-239-693-0099  
<http://www.FOXONLINE.com/repdisty>

**Tech Support**

<http://www.FOXONLINE.com/email>

# Product Change Notification

**PCN Publish Date:** 08/22/2018

**PCN#:** 101308

**Change Title:** Product Termination Finish Change

**Products Affected:**

General Part Numbers Format

Former Product Family	Former Part Format	Current Product Family	Current Part Format	Description
FQ3225B	820-frequency-xxx	C3BQ	FC3BQxxxxfrequency	3.2x2.5mm resin seal crystal, 4 pad
FQ5032B	738B-frequency-xxx	C5BQ	FC5BQxxxxfrequency	5.0x3.2mm resin seal crystal, 4 pad
FQ5032A	738A-frequency-xxx	C5AQ	FC5AQxxxxfrequency	5.0x3.2mm resin seal crystal, 2 pad
FQ1045A	735A-frequency-xxx	C8AQ	FC8AQxxxxfrequency	10.0x4.5mm resin seal crystal, 2 pad

Standard Stocking Parts: See page 2 for list of all Standard Stocking Parts.

**Description of Change to the Customer:**

Change termination finish from gold (Au) to silver (Ag)

There are no changes in solderability, electrical performance, or reliability.

**Reason for Change:** To change to a more environmentally friendly process.

**Schedule of Change:**

Last buy date for Au plated parts is 10/31/2018.

Last shipment date is 02/28/2019.

Note: Due to existing stock, there will be a transition period when product with either termination finish may be shipped until all existing material is depleted.

**Customer Impact and Response:** We sincerely hope this change will have minimal impact on our customers. If you have any questions, please contact Fox Technical Support at [www.foxonline.com/email.htm](http://www.foxonline.com/email.htm) or call 239-693-0099.

**Corporate Headquarters**

5570 Enterprise Parkway  
Fort Myers, FL 33905  
<http://www.FOXONLINE.com>

**Sales**

1-888-GET-2-FOX (1-888-438-2369) or  
1-239-693-0099  
<http://www.FOXONLINE.com/repdisty>

**Tech Support**

<http://www.FOXONLINE.com/email>

**List of Affected Standard Stocking Part Numbers:**

Part Number	New Part Number	Frequency
<a href="#">FQ1045A-3.6864</a>	FC8AQCCMC3.6864	3.686400
<a href="#">FQ1045A-4.000</a>	FC8AQCCMC4.0	4.000000
<a href="#">FQ1045A-6.000</a>	FC8AQCCMC6.0	6.000000
<a href="#">FQ1045AR-3.6864</a>	FC8AQCCMC3.6864	3.686400
<a href="#">FQ1045AR-4.000</a>	FC8AQCCMM4.0	4.000000
<a href="#">FQ1045AR-6.000</a>	FC8AQCCMM6.0	6.000000
<a href="#">FQ3225B-12.000</a>	FC3BQBBME12.0	12.000000
<a href="#">FQ3225B-16.000</a>	FC3BQBBME16.0	16.000000
<a href="#">FQ3225B-20.000</a>	FC3BQBBME20.0	20.000000
<a href="#">FQ3225B-24.000</a>	FC3BQBBME24.0	24.000000
<a href="#">FQ3225B-25.000</a>	FC3BQBBME25.0	25.000000
<a href="#">FQ3225BR-12.000</a>	FC3BQBBMM12.0	12.000000
<a href="#">FQ3225BR-16.000</a>	FC3BQBBMM16.0	16.000000
<a href="#">FQ3225BR-20.000</a>	FC3BQBBMM20.0	20.000000
<a href="#">FQ3225BR-24.000</a>	FC3BQBBMM24.0	24.000000
<a href="#">FQ3225BR-25.000</a>	FC3BQBBMM25.0	25.000000
<a href="#">FQ5032B-10.000</a>	FC5BQCCMC10.0	10.000000
<a href="#">FQ5032B-12.000</a>	FC5BQCCMC12.0	12.000000
<a href="#">FQ5032B-16.000</a>	FC5BQCCMC16.0	16.000000
<a href="#">FQ5032B-20.000</a>	FC5BQCCMC20.0	20.000000
<a href="#">FQ5032B-24.000</a>	FC5BQCCMC24.0	24.000000
<a href="#">FQ5032B-25.000</a>	FC5BQCCMC25.0	25.000000
<a href="#">FQ5032BR-10.000</a>	FC5BQCCMM10.0	10.000000
<a href="#">FQ5032BR-12.000</a>	FC5BQCCMM12.0	12.000000
<a href="#">FQ5032BR-16.000</a>	FC5BQCCMM16.0	16.000000
<a href="#">FQ5032BR-20.000</a>	FC5BQCCMM20.0	20.000000
<a href="#">FQ5032BR-24.000</a>	FC5BQCCMM24.0	24.000000
<a href="#">FQ5032BR-25.000</a>	FC5BQCCMM25.0	25.000000