

Product Discontinuation



PD_250_19

■ Last Order Date:	2020-06-30
■ Last Delivery Date:	2021-06-30

Reason: EOL

DISCONTINUED				NEW (REPLACEMENT)			
Sales name	SP number	OPN	Package	Sales name	SP number	OPN	Package
FS10R06VL4_B2	SP000095938	FS10R06VL4B2BOMA1	AG-EASY750-1	FS10R06VE3_B2	SP000100311	FS10R06VE3B2BOMA1	AG-EASY750-1
FB10R06KL4G_B1	SP000100289	FB10R06KL4G1B1BOMA1	AG-EASY2-1	FP10R06W1E3	SP000092044	FP10R06W1E3BOMA1	AG-EASY1B-1
FP15R06KL4	SP000100272	FP15R06KL4BOMA1	AG-EASY2-1	FP15R06W1E3	SP000092046	FP15R06W1E3BOMA1	AG-EASY1B-1
FP20R06KL4	SP000100273	FP20R06KL4BOMA1	AG-EASY2-1	FP20R06W1E3	SP000092041	FP20R06W1E3BOMA1	AG-EASY1B-1
FB15R06KL4_B1	SP000100290	FB15R06KL4B1BOMA1	AG-EASY2-1	FB20R06W1E3	SP000307555	FB20R06W1E3BOMA1	AG-EASY1B-1
FP10R06KL4	SP000100271	FP10R06KL4BOMA1	AG-EASY2-1	FP10R06W1E3	SP000092044	FP10R06W1E3BOMA1	AG-EASY1B-1
FS50R06YL4	SP000100285	FS50R06YL4BOMA1	AG-EASY2-1	FS50R06W1E3	SP000092043	FS50R06W1E3BOMA1	AG-EASY1B-1
FB20R06KL4_B1	SP000100291	FB20R06KL4B1BOMA1	AG-EASY2-1	FB20R06W1E3	SP000307555	FB20R06W1E3BOMA1	AG-EASY1B-1
FB10R06KL4G	SP000100276	FB10R06KL4GBOMA1	AG-EASY2-1	FP10R06W1E3	SP000092044	FP10R06W1E3BOMA1	AG-EASY1B-1
FB10R06KL4	SP000100270	FB10R06KL4BOMA1	AG-EASY1-1	FB20R06W1E3	SP000307555	FB20R06W1E3BOMA1	AG-EASY1B-1
FS30R06XL4	SP000100284	FS30R06XL4BOMA1	AG-EASY1-1	FS30R06W1E3	SP000223650	FS30R06W1E3BOMA1	AG-EASY1B-1

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended! If Infineon confirms a purchase order with a delivery date beyond last delivery date, the PD with the mentioned last ordering date still remains valid.