

Honeywell
Precision Sensors
12001 State Highway 55
Plymouth, MN 55441

January 7, 2013

Dear Valued Honeywell Customer:

Honeywell is announcing the discontinuance of part number HMC1043 3-Axis Magnetic Sensor. Recent supplier changes and re-qualification processes have attributed to the obsolescence of this part. This letter is to inform you that Honeywell will be offering a lifetime buy opportunity. This lifetime buy will continue until all existing parts (qualified at 240°C, sold under PCN-12-02). Honeywell has limited quantities which will be sold as first come, first serve to existing customers only.

The replacement for this discontinued product is the HMC1043L which will be released mid-year 2013. The HMC1043L, 3-Axis Magnetic Sensor, is projected to be 3.5mm x 3mm in size, qualified at 260°C Reflow Temperature and MSL3 tested. The new datasheet and additional information is expected to be provided by the end of Q1 2013.

End-of-life orders are non cancellable and the material is not returnable. We encourage you to order as soon as possible. Honeywell's customer service is available at 763-954-2474, fax at 763-954-2257 or email at ps.customer.support@honeywell.com.

We value your feedback, and would be happy to discuss any related issues over the phone. Please call me, Kate Flores, at 763-954-2354.

Thank you for your consideration.

Best Regards,

Kate Flores
Honeywell Precision Sensors, Customer Support Program Manager
Phone: 763-954-2354, Fax: 763-954-2257, Email: Kate.Flores@honeywell.com
www.magneticsensors.com

CC: Ray Sturm, Customer Business Manager, Tel: 763-954-2299, ray.s.sturm@honeywell.com
Eric Anderson, Product Line Manager, Tel: 763-954-2186, eric.anderson4@honeywell.com